Office	Energy Minerels and Netural D				Form C-103 May 27, 2004		
	N. French Dr., Hobbs, NM 88240			ai Resources	WELL API NO.		
	1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-02504501 5. Indicate Type o	f Lease	
<u>District III</u> 1000 Rio Brazo	District III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505				STATE X	FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505					6. State Oil & Gas		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					7. Lease Name or Unit Agreement Name Eunice Monument South Unit		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Image: A state of the state of t					8. Well Number	226	
2. Name of Operator ZA XTO Energy Inc.					9. OGRID Numbe		
 Address of Operator 200 N. Loraine, Suite 800, Midland, Tx 79701 					10. Pool name or Wildcat Eunice Monument;Grayburg San Andres		
4. Well Location							
Unit Letter O :3300_feet from theSouth line and1980_feet from theEast line							
Section 5 Township 21S Range 36E NMPM Lea County New Mexico							
11. Elevation (Show whether DR, RKB, RT, GR, etc.) Pit or Below-grade Tank Application or Closure X							
Pit typesteelDepth to Groundwater200'Distance from nearest fresh water well1000+Distance from nearest surface water_1000+							
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB						ALTERING CASING	
OTHER:				OTHER:		Y	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
11/10/04	0/04 MIRU Key Well Service PU (Adam). Intermediate csg SIP 120#. MI & racked 4,000' of 2-7/8", 6.5#, L-80, EUE, 8rd WS. ND WH. NU BOP. POOH w/2-3/8" tbg & 5-1/2" pkr. LD pkr & tie back 2-3/8" tbg. PU & RIH w/4 1/2" bit, 7 jts of 2-7/8" WS, 5-1/2" csg scraper & 118 jts of 2-7/8" WS. Tagged fill @33,951 (21' fill). POOH w/40 jts of 2-7/8" WS. Tbg was standing full of wtr, bit plugged. SWI & SDON.						
11/11/04	Installed containment pan on BOP. POOH w/85 jts of 2-7/8" WS. PU & RIH w/5-1/2" RBP, 5-1/2 pkr & 118 jts of 2-7/8", 6.5#, L-80, EUE, 8rd WS. Tried to set 5-1/2" RBP. Would not set. POOH W/2-7/8" WS & equipment. PU & RIH w/5-1/2" TS RBP, Arrowset HD pkr & 118 jts of 2-7/8" WS. Set RBP & 3640' & pkr @ 3,620'. RU Key pmp trk. Press tstd RBP to 1,500 psig for 15", held OK. Press TCA to 500 psig for 15", held OK. Rel pkr. POOH w/2-7/8" WS & pkr. Press 5-1/2" csg to 500 psig. RU Gray Wirelshe's Service. Correlated log to N.L McCullough GR/CNL dated 01/08/87. Ran GR/CCL/CBL fr 3,640' to surf. Log indicated good cmt fr 3,640' to 2,550', poor cmt fr 2,550' to 1,450'. Top of cmt @ 1,450'. Notified Midland Engineering of findings. RD Key pmp trk & Gray Wireline. SWI & SDON.						
11/12/04	RU Key vacuum trk to intermediate csg (120#). Flowed 10 bbls back to trk before blowing dwn. RD Key vacuum trk. Replaced 2" valve on int csg riser. RIH w/47 jts of 2-7/8" WS & dumped 100# sack of sand dwn tbg to set on top of RBP. RU Key pmp trk. Pmpd 30 bbls dwn tbg & circulated back up production csg to trk. RD Key pmp trk. POOH w/2-7/8" WS. SWI & SDON.						
11/13/04		nt squeeze approval.					
11/14/04	SDF Saturday.						
11/15/04 SDF Sunday. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-							
grade tank has been/will be constructed of closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .							
SIGNATURE	: Juthan	/	_TITLE	Regulatory Tech	D	ATE2/3/05_	
Type or print		Δ	E-mail add			ephone No.	
For State Use Only							
APPROVED BY: Harry W. Wink OCIFIELD REPRESENTATIVE II/STAFF MANAGER							
Conditions of Approval (if any):							

EUNICE MONUMENT SO.UNIT #226 <= continued=> XTO Energy Inc.

- 11/16/04 RU Key pmp trk. Press 5-1/2" csg to 500 psig. Attempted to pmp dwn 8-5/8" intermediate csg, wtr leaking around wellhead. RD Key pmp trk. RIH w/2-7/8", 6.5#, J-55, EUE, 8rd OE tbg. POOH LD 2-7/8" tbg. RIH w/2-3/8", 4.7#, J-55, EUE, 8rd Duoline tbg. STD POOH LD 2-3/8" tbg. SWI & SDON.
- 11/17/04 POOH & LD 115 jts of 2-3/8", 4.7#, J-55, EUE, 8rd Duoline tbg. ND BOP. NU WH. SWI. RDMO PU. Will dig out wellhead when weather clears & continue repair process.
- 11/18/04 SD due to weather.
- 11/19/04 SD due to weather.
- 11/20/04 SD waiting to dig wellhead out.
- 11/21/04 SD waiting to dig wellhead out.
- 11/22/04 SD waiting to dig wellhead out.
- 11/23/04 SD due to weather. Drop fr DOR until operations resume.
- 2/1/05 MIRU Key Well Service (Adam). Bull Dog MI & Racked 3700' of 2-7/8", 6.5#, L-80, EUE, 8rd tbg WS(A). ND WH. NU BOP. PU & RIH w/114 jts of 2-7/8" WS to RBP. RU Key pmp trk & vac trk. Circ snd off of RBP w/60 BW. RD Key trks. Latched on to RBP @ 3,640'. POOH & LD tbg & RBP. Chg'd out rams on BOP for 2-3/8" IPC tbg. SWI & SDON. Notified Sylvia Dickey w/NMOCD of MIT test for 02/01/05.
- 2/2/05 RU Bo Monk pipe tsters. Tstd 2-3/8", 4.7#, J-55, EUE, 8rd IPC tbg to 5,000 psig below slips. RIH w/5-1/2" Guiberson G-6 pkr w/XL on/off tool, 1.781 F SS nipple & 2-3/8" WL entry guide w/pmp out plug on 118 jts 2-3/8" IPC tbg. Top 2-3/8" jt is new. Tsters found threads bad in 1 jt. RD Bo Monk pipe tsters. Set 5-1/2" pkr @ 3,655' & rel on/off tool. RU Key pmp trk & transport. Circ hole w/100 BW w/42 gals Champion pkr fluid. Latched onto pkr. ND BOP. NU wellhead. Pressd 5-1/2" TCA to 420 psig for 30" & Performed MIT test for NMOCD (test was witnessed by NMOCD personnel Buddy Hill), held ok. Pressd 2-3/8" tbg to 2,100 psig & ruptured pmp out plug. RD Key trks. RDMO PU. RWTI.



. . <u>.</u>

1