State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

| DISTRICT I 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505 | WELL API NO. 30-025-07564 |
|--|--|
| DISTRICT II | 5. Indicate Type of Lease |
| 1301 W. Grand Ave, Artesia, NM 88210 | STATE X FEE |
| DISTRICT III | 6. State Oil & Gas Lease No. |
| 1000 Rio Brazos Rd, Aztec, NM 87410 | |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A | NORTH HOBBS (G/SA) UNIT |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) | Section 33 8. Well No. 211 |
| 1. Type of Well: Oil Well Gas Well Other Injector | |
| 2. Name of Operator Occidental Permian Ltd. | 9. OGRID No. 157984 |
| 3. Address of Operator | 10. Pool name or Wildcat HOBBS (G/SA) |
| 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 | |
| 4. Well Location Unit Letter C: 330 Feet From The NORTH 2310 Fee | t From The WEST Line |
| Olite Letter C . 350 Post Tom The Post Time 1 | |
| 11. Elevation (Show whether DF, RKB, RT GR, etc.) | LLA COMM) |
| 3642' GR | |
| Pit or Below-grade Tank Application or Closure | |
| Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water | |
| Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | X ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP | NO DULIO O ADANDONIMENTE |
| | NS. PLUG & ABANDONMENT |
| PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN | |
| | |
| OTHER: OTHER: | NT JOB |
| OTHER: OTHER: OTHER: OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the complete of th | NT JOB |
| OTHER: OTHER: OTHER: OTHER: OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU. Pull injection equipment. | NT JOB |
| OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: RUPU. Pull injection equipment. Plug back w/sand from4228' to 4205'. Stimulate perfs 4058-4205 w/3500 g 15% NEFF HCL acid | s, including estimated date of starting any completion or recompletion. |
| OTHER: RUPU. Pull injection equipment. Plug back w/sand from4228' to 4205'. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKI | s, including estimated date of starting any completion or recompletion. |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKR 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. | a, including estimated date of starting any completion or recompletion. 3. See 4044. |
| OTHER: RUPU. Pull injection equipment. Plug back w/sand from4228' to 4205'. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKI | s, including estimated date of starting any completion or recompletion. |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location. Rig Up Date: 01/27/2005 | a, including estimated date of starting any completion or recompletion. 3. See 4044. |
| 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location. | a, including estimated date of starting any completion or recompletion. Q30 sqqoH Q3A:7774 |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location. Rig Up Date: 01/27/2005 | a, including estimated date of starting any completion or recompletion. 3. See 4044. |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location. Rig Up Date: 01/27/2005 Rig Down Date: 02/02/2005 | os, including estimated date of starting any completion or recompletion. Oscillatoria (1990) Oscillatoria (1990) |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location. Rig Up Date: 01/27/2005 Rig Down Date: 02/02/2005 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative | s, including estimated date of starting any completion or recompletion. R set 4044'. GOOD SQQOH GOO |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. 2. Plug back w/sand from4228' to 4205'. 3. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. 4. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF 5. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. 6. RDPU. Clean Location. Rig Up Date: 01/27/2005 Rig Down Date: 02/02/2005 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan | is, including estimated date of starting any completion or recompletion. R set 4044'. GOOD That any pit or below-grade tank has been/will be the OCD-approved |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. Plug back w/sand from4228' to 4205'. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 01/27/2005 Rig Down Date: 02/02/2005 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE Workover Constructed. | s, including estimated date of starting any completion or recompletion. R set 4044'. GOOD That any pit or below-grade tank has been/will be be OCD-approved Inpletion Specialist DATE 12/04/2005 |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. Plug back w/sand from4228' to 4205'. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 01/27/2005 Rig Down Date: 02/02/2005 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE Workover ConTYPE OR PRINT NAME Robert Gilbert E-mail address: robert_gilbert@oxy.com | s, including estimated date of starting any completion or recompletion. R set 4044'. GOOD That any pit or below-grade tank has been/will be be OCD-approved Inpletion Specialist DATE 12/04/2005 |
| OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU. Pull injection equipment. Plug back w/sand from4228' to 4205'. Stimulate perfs 4058-4205 w/3500 g 15% NEFE HCL acid. RIH 5.5" UNI VI pc pkr, XL on off tool w/1.875 ss "F" nipple 127 jts 2-7/8" Duoline tbg. PKF. Circ csg w/90 bbl pkr fluid. Load and tst csg to 540 psi for 30 min and chart for the NMOCD. Rig Up Date: 01/27/2005 Rig Down Date: 02/02/2005 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan. SIGNATURE Workover Constructed or TITLE Workover Constructed or TITLE Workover Constructed or Closed according to NMOCD guidelines TITLE Workover Constructed or TITLE Workover Constructed or TITLE Workover Constructed or Closed according to NMOCD guidelines TITLE Workover Constructed or TITLE Workover Constructed Or Closed according to NMOCD guidelines TITLE Workover Constructed Or Closed according to NMOCD guidelines TITLE Workover Constructed Or Closed according to NMOCD guidelines TITLE Workover Constructed Or Closed according to NMOCD guidelines TITLE Workover Constructed Or Closed according to NMOCD guidelines TITLE Workover Constructed Or Closed according to NMOCD guidelines TITLE Workover Constructed Or Closed States and Closed States a | is, including estimated date of starting any completion or recompletion. R set 4044'. GOOD That any pit or below-grade tank has been/will be be OCD-approved Inpletion Specialist DATE 02/04/2005 TELEPHONE NO. 505/397-8206 |

