Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
• <u>District I</u> • Energy, Minerals and Natural Resources	WELL API NO. May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Graud Ave. Artesia NM 88210 OIL CONSERVATION DIVISION	36-045-32403
1301 W. Graud Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Sonto Eq. NM 87505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OBJECT GBACK TO A	7. Lease Name or Unit Agreement Name Johnston Com B
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM CARE) FOR SUCH 🖇 🥎 👘	(APD filed with BLM NMNM 080112)
PROPOSALS.) 1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other	8. Well Number
En 2000 CO	2 M
2. Name of Operator BP AMERICA PRODUCTION COMPANY	9. OGRID Number 000778
3. Address of Operator	10. Pool name or Wildcat
P.O. BOX 3092 HOUSTON, TX 77079-2064	Basin Dakota & Blanco Mesaverde
4. Well Location	
Unit Letter N_: 1100 feet from the South Line a	nd 1790 feet from the West line
Section 11 Township 28N Range 09W	
11. Elevation (Show whether DR, RKB, RT, GR, et 5783'	
Pit or Below-grade Tank Application 🗋 or Closure 🗌	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
	Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO TEMPORARILY ABANDON CHANGE PLANS COMMENCE D	RK
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	
	_
OTHER: DOWNHOLE COMMINGLING Image: Complete com	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
On 06/01/04 BP America Production Company submitted an application for permit to drill and complete the subject well into the Basin	
Dakota; produce the well in order to establish a production rate, isolate the zone, then add the Blanco Mesaverde and commingle production Downhole. APD was approved 10/05/2004. BP now seeks NMOCD approval to Downhole commingle production in the	
subject well as per procedure on reverse side of this Form.	
The Basin Dakota (71599) & the Blanco Mesaverde (72319) Pools are Pre-Approved for Downhole Commingling per NMOCD Order R - 11363. The working and overriding royalty interest owners are different in the proposed commingled pools; therefore notification of this	
application was submitted by copy of this application to all interest owners via certified mail (return receipt)	
Production is proposed to be based on a fixed percentage. We will complete in the Basin	
the Blanco Mesaverde, establish a production rate; drill out the bridge plug and commingle production downhole. The deliverability test will be performed on the combined zones and MV rate will be subtracted from the total well stream to establish the DK rate.	
Commingling Production Downhole in the subject well from the proposed pools will not reduce the value of the total remaining	
production	
DWC 1735AZ	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-	
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit] or an (attached) alternative OCD-approved plan [].
SIGNATURE worn + lava TITLE Regulatory Anal	<u>Jost DATE 12/30/2004</u>
Type or print name Cherry Hlava E-mail address: hlavacl@bp.com For State Use Only	$\frac{\text{Telephone No. 281-366-4081}}{\text{JAN} - 3 \ 2005}$
For State Use Only	AND COLOR DIST #3
APPROVED BY:	DATE DATE
Conditions of Approval (if any): V/V	

(OUER)

Sign. 1244 المواجوع فالمعاد والأمريوة لوقا ويرافعون الجير もっきこくせ £ . Carl Colora 1. Run TDT/CBL 2. Perforate DK 3. Frac the DK (Slick Water) 4. RU SU. Clean out DK frac, perform flow test, collect DK gas sample, and obtain 12-hour BHPBU 5. Set bridge plug to isolate MV from DK formation 6. Perforate and frac (2- Stage N2 Foam) the MV Formation 7. Clean out MV frac, perform flow test for production allocation and collect MV gas sample 8. Drill out isolation plug, commingle MV/DK and clean out wellbore to PBTD. 9. Run completion string. RDSU 5 1 B 1 1.5100 10. Put well on Line *i*, ` 07 1 . . . ; , 1 en la carrage al ate e e 1111 A.C. · · · · · · · · ALCOC. and the second . • a second a second s 1 1 1 1 ^m4 i 2 · · · · · · 8 2 A. n -Lingen transformer states a 51 2 • ٠.. ; ar 1 , . and a second second state of the second and the second second second second second second second second second A second secon A second secon . ' · : **ч**. . the start with . .. ب الجارو ال

المراجعية". الذي المراجعة في حاليه من المراجعة في من المراجعة في ومن الأطل ممركة "ممركة المراجع في مراجعة". 4 معلاً المراجعة المراجعة من من المراجعة المراجعة في من من المراجعة من الأطل من ممركة المراجعة المراجعة المراجع 1 مع مالية المراجعة المراجعة المراجعة المراجعة المراجعة من معاطلة المراجعة المراجعة المراجعة المراجعة المراجعة ا

در العلمي المراجع المراجع المراجع المراجع المراجع المراجع المربع المحمد المراجع في المراجع المراجع المراجع الم المراجع والاستراجع المراجع المراجع المراجع المراجع والمراجع في المحمد المراجع المراجع المراجع المراجع المراجع ف المراجع المراجع في المراجع المراجع المراجع المراجع المراجع المحمد المراجع المحمد المراجع المراجع المراجع المراجع

e serve petropolo de la construcción de la serve terre estructura en la para estata de la construcción en l'acte La construcción

Beneric and a substantial and the second states of Bana and the second states of the second states and the second states and the second states and the second states and the second states are second states and the second states are second states and the second states are second states

ч. н.

