

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35615
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other Plug & Abandon		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator CONCHO RESOURCES INC.		6. State Oil & Gas Lease No.
3. Address of Operator 550 W. TEXAS, SUITE 1300 MIDLAND, TX 79701		7. Lease Name or Unit Agreement Name Largo "36" State
4. Well Location Unit Letter G : 1980 feet from the North line and 1980 feet from the East line Section 36 Township 10S Range 32E NMPM County Lea		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4299 GR		9. OGRID Number 193407
		10. Pool name or Wildcat 'Cuerno Largo; Penn

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2-04-04 RIH w/CIBP set @ 9112' capped w/25 sx cmt.

2-05-04 RIH w/CIBP set @ 6642 capped w/25 sx cmt.

2-06-04 Welded on csg. nipple. Pulled on csg. Free above 3450'. Cut off 3791'. Pulled loose.

2-09-04 Pumped 40 sx plug @ 3855', inside 5 1/2" csg.

2-10-04 RIH & tag @ 3628'. POH & spot 35 sx @ 1717' - 1600'. POH & spot 35 sx w/ 2 1/2% CaCl @ 486'.

2-11-04 RIH & tag @ 357'. POOH & spot 20 sx @ 60' to surface. RD Cut off wellhead & anchors. Install dry hole marker, level pit & cellar, move out

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brenda Coffman

TITLE REGULATORY ANALYST

DATE 02/18/2004

Type or print name BRENDA COFFMAN

E-mail address:

BCOFFMAN@CONCHORESOURCES.COM

Telephone No. (432)685-4373

(This space for State use)

APPROVED BY

Larry W. Wink

TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any:

FEB 18 2005