

New Mexico Oil Conservation Division, District I
1625 N. French Drive
Hobbs, NM 88240

Form 3160-5
(JUNE 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil ☐ Gas ☐
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No. P. O. Box 1030

Roswell, New Mexico 88202-1030 505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 1980' FWL

Section 18-23S-32E

5. Lease Designation and Serial No.

NM-~~10020~~ 105929

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

SDE 18 Federal #1

9. API Well No.

30-025-25622

10. Field and Pool, or Exploratory Area

Sand Dunes Delaware East

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plug
☐ Casing Repair
☐ Altering Casing
☐ OTHER

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

02/08/05: Mayo Marrs notify BLM. MIRU. NUBOP. Move in steel pit per BLM & OCD rules. Test tbg to 500# w/pump set. Unset pump. POOH w/110 - 1", 101 - 7/8" & 123 - 3/4" rods.

02/09/05: NDWH. NUBOP. POOH w/130 stnds. LD 5 jnts. RIH & set CIBP @ 8325'. Close in well.

02/10/05: Dump 35' cmt on top of CIBP @ 8325' - 8290'. RIH w/tbg & circ 10# mud. POOH & spot 25 sxs @ 6849' - 6649'. POOH & spot 25 sxs @ 4700' - 4500'. POOH. Close in well.

02/11/05: RIH & tag @ 4500' w/tbg. POOH & spot 25 sxs @ 2600' - 2400'. POOH & spot 25 sxs @ 1016'. POOH. WOC. RIH & tag @ 830'. POOH & spot 10 sxs @ 60' to surface.

02/14/05: RD. Cut off wellhead & anchors. Install dry hole marker. Level cellar. Empty steel pit.

Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed *Kenneth Britte*

Title Production Records

Date 02/14/05

(This space for Federal or State office use)

Approved by ORIG. SGD.) DAVID K. GLASS

PETROLEUM ENGINEER

Date FEB 15 2005

Conditions of approval, if any: