Form 3160-5 (April 2004)

3a Address

1625 N. French Drive

Hobbs, NM 88240 UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NM-81633 6. If Indian, Allottee or Tribe Name

	SU	NDF	iy N	OTIC	ES	AND	RE	PORT	SC	N	WELL	.S
Do	not	use	this	form	for	propos	als	to drill	or	to	re-en	ter an
aba	ando	ned	well.	Use	Fort	n 3160	-3	(APD) 1	or e	suct	nron	neale

7. If Unit or CA/Agreement, Name and/or No. Checkerboard 23 Federal

SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Wel Gas Well Other

2. Name of Operator EOG Resources Inc.

PO Box 2267 Midland, TX, 79702

4. Location of Well [Footage, Sec., T., R., M., or Survey Description]

Unit Letter 1, 1980 FNL, 990 FWL Section 23, Township 22-S, Range 32-E 9. API Well No.

3b. Phone No. (include area code) 432-561-8600

30-025-32627 10. Field and Pool, or Exploratory Area

> Redtank, Delaware, West 11. County or Parish, State

8. Well Name and No.

Lea, New Mexico

12.	CHECK	APPROPRIATE	BOX(ES) TO	INDICATE	NATURE	OF NOTICE,	REPORT,	OR OTHER	DATA
						,	,		

			. ,	
TYPE OF SUBMISSION		TYI	PE OF ACTION	
Notice of Intent ✓ Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other
13 Deccribe Proposed on Communication	40			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- 1. Notify Kathy with BLM 24 hours prior to MI. & RU.
- 2. TBG & PKR stuck @ 8215 cut tbg @ 8200.
- 3. Notified Gary Gourley with BLM. Allowed to spot 25sx Plug @ 8200 (Delaware, TOF) Spot 25sx plug from 8200 - 8000 WOC. Tag @ 7890
- 4. Displace hole with MLF 9.5# Brine W/25# Gel P/BBL
- 5. Spot 55sx plug from 4900-4400 (8 5/8 Shoe) WOC. Tag @ 4390
- 6. Cut 5 1/2 CSG. @ 2700 no pull press up to 2000 psi. Spot 25sx plug from 2750-2500 WOC. Tag @ 2523.
- 7. Perf. @ 1150 Sqz. 100sx plug from 1150-800 (13 3/8 Shoe T-Salt) WOC Tag @ 796
- 8. Perf. @ 300 Circ. 75sx CMT. Down 5 1/2 up through 8 5/8 Annulus csg. WOC Tag @ Surf.
- 8. Install dry hole marker. P&A Complete 2-9-05

Approved as to plugging of the well born Ciability under bond is retained until surface restoration is completed.

I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Consultant Signature 02/14/2005 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE CORIG SGD. DAVID & GLASS FEB 2 2 2005 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW

(Instructions on page 2)