

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

March 4, 2004

WELL API NO. 30-025-04770
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name H.T. Mattern (NCT-A)
8. Well Number 3
9. OGRID Number
10. Pool name or Wildcat Penrose Skelly, Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Chevron USA Inc

3. Address of Operator

15 Smith Rd, Midland, TX 79705

4. Well Location

Unit Letter P : 660 feet from the South line and 660 feet from the East line

Section 24 Township 21-S Range 36-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL P Sect 24 Twp 21S Rng 36E Pit type Steel Depth to Groundwater 150 Distance from nearest fresh water well Over 1000'

Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;

660 feet from the South line and 660 feet from the East line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hours Prior to MI & RU.
2. Set 7 CIBP @ 3620 Spot 50sx Plug 3620 - 3500 (Grayburg, Top of 7 Liner) WOC Tag.
3. Displace hole W/MLF, 9.5 # Brine with 12# gel P/BBL.
4. Spot 50sx plug 2900-2700 (Yates).
5. Perf 4 holes @ 1300 SQZ 115sx plug 1300-1100 (T-Salt) WOC Tag.
6. Perf 4 Holes @ 375 SQZ 125sx plug 375-200 (13 3/8 Shoe) WOC Tag.
7. 10sx Surf, Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Jimmy Bagley TITLE Consultant DATE 2/24/05  
Type or print name Jimmy Bagley E-mail address: Telephone No. 432-561-8600

(This space for State use)

APPROVED BY Harry W. Wink TITLE DATE  
Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST  
BE NOTIFIED 24 HOURS PRIOR TO THE  
BEGINNING OF PLUGGING OPERATIONS.