

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

**DISTRICT I**  
1625 N. French Dr., Hobbs, NM 88240

1220 South St. Francis Dr.  
Santa Fe, NM 87505

**DISTRICT II**  
1301 W. Grand Ave, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.  
30-025-07536

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

7. Lease Name or Unit Agreement Name

NORTH HOBBS (G/SA) UNIT  
Section 32

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

8. Well No. 441

2. Name of Operator

Occidental Permian Ltd.

9. OGRID No. 157984

3. Address of Operator

1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200

10. Pool name or Wildcat HOBBS (G/SA)

4. Well Location

Unit Letter P : 660 Feet From The SOUTH 660 Feet From The EAST Line  
Section 32 Township 18-S Range 38-E NMPM LEA County

11. Elevation (Show whether DF, RKB, RT GR, etc.)  
3642' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type \_\_\_\_\_ Depth of Ground Water \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water

Pit Liner Thickness \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ Multiple Completion ☐  
OTHER: \_\_\_\_\_ ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: \_\_\_\_\_ ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU. Pull ESP equipment. Fish RBP @4244'.
2. Stimulate perms 4112-4244 w/4000 g 15% NEFE HCL acid.
3. Run CNL/GR from PBDT @4244' to 3240'. Perforate the following intervals 4071-78, 4085-88 using 2 spf, 120 deg ph. (26 holes)
4. Stimulate new perms w/840 g 15% NEFE HCL acid.
5. RIH Reda ESP equipment on 127 jts 2-3/8" tbg w/drain valve. Intake set @4016'.
6. RDPU. Clean Location.

Rig Up Date: 02/02/2005

Rig Down Date: 02/09/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE

*Robert Gilbert*

TITLE Workover Completion Specialist

DATE 02/10/2005

TYPE OR PRINT NAME Robert Gilbert

E-mail address: robert\_gilbert@oxy.com

TELEPHONE NO. 505/397-8206

For State Use Only

APPROVED BY

*Harry W. Wink*

CONDITIONS OF APPROVAL IF ANY:

TITLE FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

MAR 02 2005