## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION			
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-23007		
DISTRICT II	Z		5. Indicate Type of Lease	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X	
DISTRICT III			6. State Oil & Gas Lease No.	•	
1000 Rio Brazos Rd, Aztec, NM 87410		•			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 32		
Type of Well:     Oil Well X Gas Well Other			8. Well No. 121	121	
Name of Operator     Occidental Permian Ltd.	9. OGRID No. 157984				
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)	
1017 W. Stanolind Rd., HOBBS,					
4. Well Location					
Unit Letter <u>E</u> : <u>1730</u>	Feet From The NORTH		et From The WEST	Line	
Section 32	Township 18-S  11. Elevation (Show whether DF, RK	Range 38-	E NMPM	LEA County	
	3635' GL				
Pit or Below-grade Tank Application or Closure					
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
I to Enter Intertions introduce Talk. Totalic outs, Constituction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			ALTERIN	G CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP			PNS. PLUG &	ABANDONMENT	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB					
OTHER:				ndon Well X	
			Temporarily Abar	luon vven	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. RUPU. Pull production equipme	a de la casa de la cas La casa de la casa de				
2. Set 5.5" CIBP @4059'. Set 2 <sup>nd</sup>					
3. Tst csg to 1000 psi. Held OK.					
<ul><li>4. Circ csg w/100 bbl pkr fluid. Tst csg to 550 psi for 30 min and chart for the NMOCD.</li><li>5. RDPU. Clean Location.</li></ul>					
Well is T&A'd					
		, /	· 4	1 1 2 h	
Rig Up Date: 02/14/2005 Rig Down Date: 02/17/2005 This Approval of Temporary 2/17/10 Abandonment Expires					
Rig Down Date: 02/17/2005 This Approval of Temporary 2/17/2005					
	Abandonment Expired.	,	<b>\</b> .		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be					
constructed or		_			
closed according to NMOCD guidelines	, a general permit	or an (attached) alternativ	ve OCD-approved		
Plan plan					
SIGNATURE X XVIII	- thu	TITLE Workover Cor	npletion Specialist DA	TE 03/01/2005	
TYPE OR PRINT NAME Robert Gill	bert E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO	D. 505/397-8206	
For State Use Only	1.1-			MAR 0 2 2005	
APPROVED BY Jayli	I. WINK	TITLE		MAR 0 2 2005	
		_			

