Office State of New Mexico Office From Minorals and Natural Because of	Form C-103	
District I District I	May 27, 2004	
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-005-20808 5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505	1 1	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District LY.	STATE FEE X	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 023290	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Sanders	
1. Type of Well: Oil Well Gas Well X Other	8. Well Number	
2. Name of Operator	9. OGRID Number	
Energen Resources Corporation	162928	
3. Address of Operator	10. Pool name or Wildcat	
3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705	Cato San Andres West	
4. Well Location		
Unit Letter E: 1900 feet from the North line and	660 feet from the West line	
Section 8 Township 8-S Range 30-E	NMPM Chaves County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit on Palmy and Tark A. P. d. D. Ch.		
Pit or Below-grade Tank Application or Closure	C>, 52,00	
Pit type Depth to Groundwater Distance from nearest fresh water well Dis		
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	on Material	
	*	
12. Check Appropriate Box to Indicate Nature of Notice,	D O.1 D.	
12. Check appropriate box to indicate that the of 140tice,	Report, or Other Data	
	* *	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF: ALTERING CASING	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	SEQUENT REPORT OF: ALTERING CASING	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER:	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT D Pertinent dates, including estimated date	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened we11, RU swab. Made 3 runs, recovered 6 BPW and we1	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger.	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well.	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING COMMENCE DRILLING COMPLETION OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1	SEQUENT REPORT OF: X	
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars, 124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING COMMENCE DRILLING COMPLETION OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars,124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars,124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars.124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been will be constructed or closed according to NMOCD guidelines , a general permit [SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars.124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been will be constructed or closed according to NMOCD guidelines , a general permit [SIGNATURE]	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 · Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 · Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars, 124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI I hereby certify that the information above is true and complete to the best of my knowledge grade tank has ben'n the information above is true and complete to the best of my knowledge grade tank has ben'n the constructed or closed according to NMOCD guidelines , a general permit SIGNATURE E-mail address: Type or print name Carolyn Larson	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 - Opened well, RU swab. Made 3 runs, recovered 6 BPW and wel acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 - Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars.124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been fill be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Regulator E-mail address: Type or print name Carolyn Larson OC FIELD REPRESENTATIVE OC FIELD REPRESENTATIVE	SEQUENT REPORT OF: X	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 1/21/04 · Opened well, RU swab. Made 3 runs, recovered 6 BPW and well acidized w/ 2500 gals of 15% NEFE HCL w/additives. RD Schlumberger, swab, ND wellhead. Unset Lok-set pkr and SI well. 1/24/04 · Opened well. POOH w/96 jts tubing, Lok-Set packer and 3 jt and tubing. ND BOP and NU wellhead. RIH w/strainer nipple on a 20-1 fit pump #QH-1046, "K" sinkerbars, 124 "KD" rods, 8' grade "KD" pony r 3240'. SO, HO, L&P tubing to 500# w/11 bbls of 2% KCL water. Built r the pumping unit. Well wouldn't pump. SI I hereby certify that the information above is true and complete to the best of my knowledge grade tank has ben'n the information above is true and complete to the best of my knowledge grade tank has ben'n the constructed or closed according to NMOCD guidelines , a general permit SIGNATURE E-mail address: Type or print name Carolyn Larson	SEQUENT REPORT OF: X	

Submit 3 Copies To Appropriate District State of New Mexic	
District I	
1625 N. French Dr., Hobbs, NM 87240 District II OH. CONSCERNATION F	WELL API NO. 30-005-20808
1301 W Grand Ave Artesia NM 88210 OIL CONSERVATION L	AVISION CY
District III 1220 South St. Franc 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 8750	1
District IV	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 023290
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR FOR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	PLUG BACK TO A Candons
1. Type of Well: Oil Well Gas Well X Other	8. Well Number
2. Name of Operator	9. OGRID Number
Energen Resources Corporation	162928
3. Address of Operator	10. Pool name or Wildcat
3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705	Cato San Andres West
4. Well Location	
Unit Letter E: 1900 feet from the North	line and 660 feet from the West line
	ge 30-E NMPM Chaves County
11. Elevation (Show whether DR,	RKB, RT, GR, etc.)
Pit.or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh war	er well Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material
TEMPORARILY ABANDON	SUBSEQUENT REPORT OF: MEDIAL WORK
• · · · · · · · · · · · · · · · · · · ·	HER:
 Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion. 1/25/04 - Opened well, removed stuffing box. Added a cunseated. Respaced the pump to a light tag, RU a hot obbls of 20 KCl waaater. Respace pump and well pumped of 1/26/04 - The 24 hour well test on the rod pump was 90 	mpletions: Attach wellbore diagram of proposed completion 8/4"x 6' and a 3/4" x2" pony rod, but pump oiler on the tubing. L&P the tubing to 500# w/9 good.
1/20/05 - Set Lufkin C80D-116-48 pumping unit with 10 P 2/17/05 - 24 hr well test was 0 BO, 3 BW, 218 MCF. FIN	IP Westinghouse motor . Tested anchors. IAL REPORT
I hereby certify that the information above is true and complete to the best grade tank has been will be constructed or closed according to NMOCD guidelines	of my knowledge and belief. I further certify that any pit or below-, a general permit or an (attached) alternative OCD-approved plan
SIGNATURE aloly Jasa TITLE	Regulatory Analyst DATE 3/18/05
Type or print name Carolyn Larson CRIGINAL SI	address: clarson@energen.com
For State Use Only GARY W. WI	NK PRESENITATIVE IÚSTAFE MANAGES
APPROVED BY TITLE	DA MAR 2 3 2005
Conditions of Approval, if any:	MAK 2 3 2005