Submit 3 Copies To Appropriate District Office District I	State of New Mexico		Form C-103 March 4, 2004	
1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-06922		
District III 1220 South St. Francis Dr.		5. Indicate Type of		
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505		6. State Oil & Gas		
1220 S. St. Francis Dr., Santa Fe, NM 87505			o. State on a das	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name H.T. Mattern (NCT-B)	
1. Type of Well: Oil Well Gas Well  Other			8. Well Number	
2. Name of Operator			0.000	10
Chevron USA Inc			9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat	
15 Smith Rd, Midland, TX 79705			Eumont-Gas	
4. Well Location				
Unit Letter C: 660 feet from the North line and 1980 feet from the West line				
Section 31	Township 21-S Ra	ange 37-E	NMPM Lea	County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)				
Pit Location: UL C Sect 31 Twp 21S Rng 37E Pit type Steel Depth to Groundwater 100 Distance from nearest fresh water well Over 1000'				
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng;				
feet from theline andfeet from theline (Steel Tank)				
	neet nom thennee (S	neer rank)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		LTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		LUG AND
	MULTIPLE   COMPLETION	CASING TEST AN		BANDONMENT
OTHER:		OTHER:		П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated details.)				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Notified OCD 24 Hours Prior To MI & RU		<u>ាំ.កេរ្</u> តា	royed as to pluggir	ng of the Well Bore.
2. Set 5 1/2" CIBP @ 3700' Spot 25sx Plug 3700-3500 (Penrose) WOC Tag.@ 3494 3. Displace Hole with 9.5# Brine With 12.5# Salt Gel Per Barrel  Liability under bond is retained until				
l. Spot 25sx Pulg 2800-2600 (Yates B-Salt)				
5. Spot 25sx Plug 1300-1100 (T-Salt) 6. Perf 4 Holes @ 475' Sqz 100sx Plug 475-2	00 (8 5/8 Shoe) WOC Tag @ 201			_
. Tusx Surr, Install Dry Marker 3-10-05				
I hereby certify that the information abourned tank has been/will be constructed or close	ove is true and complete to the be od according to NMOCD guidelines	st of my knowledge ], a general permit [] (	e and belief. I further our an (attached) alternati	ertify that any pit or below- ve OCD-approved plan .
SIGNATURE	TITLE_	Consultan		OATE 3-10-05
Type or print name Simmy Bagley	E-mail ad	dress:	Tele	phone No. 432-561-8600
(This space for State use)				
APPPROVED BY LOUIS TITLE DEPRESENTATIVE II/STAFF MANAGER				
APPPROVED BY THE FIELD REPRESENTATIVE II/STAFF MAN DATE MAR 2 3 2005				
				~~