Submit 3 Copies To Appropriate District	State of New M	lexico	Form C-103
Office . District I	Energy, Minerals and Nat		May 27, 2004
District 1 1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-36914
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.			STATE 🗌 FEE 🔀
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES	AND REPORTS ON WELL	<u>s</u>	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		ALPHA "7"	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other		8. Well Number 2	
2. Name of Operator PATTERSON PETROLEUM LP		9. OGRID Number 141928	
3. Address of Operator P.O. DRAWER 1416 SNYDER, TX 79550		10. Pool name or Wildcat WILDCAT; MISSISSIPPIAN	
4. Well Location	dala mayor di s		
Unit Letter D : 6	595 feet from the NOF	RTH line and 33	0feet from theWESTline
Section 7	Township 15S	Range 34E	NMPM County LEA
	. Elevation (Show whether Di	<u> </u>	
Pit or Below-grade Tank Application 🗌 or Clo	sure 🗌		
Pit typeDepth to Groundwater	Distance from nearest fresh	water well Dist	ance from nearest surface water
	Below-Grade Tank: Volume		nstruction Material
	·		
12. Check Appl	ropriate Box to Indicate N	valure of motice,	Report of Other Data
	NTION TO: LUG AND ABANDON HANGE PLANS ULTIPLE COMPL	SUB REMEDIAL WORI COMMENCE DRI CASING/CEMENT	
OTHER: 13 Describe proposed or completed	operations (Clearly state all	OTHER:	l give pertinent dates, including estimated date
of starting any proposed work). or recompletion.	SEE RULE 1103. For Multi	ple Completions: At	ach wellbore diagram of proposed completion
SEE ATTACHED DAILY COMPL	ETION REPORT.		
			A CARLER AND
			(21 - 2000 1114 - 20
			NED
			h-Hobbs
			100 (m)
I hereby certify that the information abov grade tank has been/will be constructed or closed	e is true and complete to the b d according to NMOCD guidelines	est of my knowledge □, a general permit □	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .
SIGNATURE Man 19	TITLE	ENGINEER	DATE03/10/2005
Type or print name Nolan von Roeder			
For State Use Only		PETROLEUMEN	ENNEER elephone No. 325-573-1938
APPROVED BY:	TITLE	1	MAR 78 4 2005
Conditions of Approval (if any):			
(it uny).			

۲

ALPHA "7" NO. 2 Sec. 7, T-15-S, R-34-E Lea County, New Mexico

DAILY COMPLETION REPORT

- 01/06/05 MIRUPU. NUBOP. Picked up 4-3/4" bit & scraper. Began picking up new 2-7/8" L80 tubing from the rack. SWIFN.
- 01/07/05 Continued picking up tubing to depth of 13,628'. Rigged up pump truck & circulated well with 290 bbls of 10#/gal brine water. Pressured up on casing & BOP to 3000 psi (tested good). Began pulling out of the hole with tubing. SWIFN.
- 01/08/05 Finished pulling tubing. Laid down bit & scraper. Rigged up wireline truck & ran in hole with GR/CBL/CCL. Had good cement across pay zones. PBTD @13,982', top of cement @7150'. Rigged down wireline truck. Will perforate Monday morning.
- 01/10/05 Rigged up pump truck & loaded casing with 15 bbls of 10#/gal brine water. Rigged up wireline truck. Ran in the hole with 3-3/8" perforating gun. Perforated Morrow Sand @13,528-36' & 13,584-93'. Pulled out of the hole with wireline & rigged down. Picked up 5½" 10K Arrow-set packer w/2-7/8" N80 sub, 2.313" XN profile with wireline re-entry guide, 2.313" X profile & on-off tool. Set packer @13,428' & re-entry @13,432'. Closed pipe rams & rigged up pump truck on casing. Tested packer good @2000 psi. NDBOP. Nipple up 10K tree, tested seal good @8000 psi. Hooked up flowline to test tank. SWIFN.
- 01/11/05 Had 0 psi on tubing. Rigged up swab. Had fluid @200' from the surface on first run. Swabbed fluid level down to 10,500' from the surface. Recovered 79 bbls of brine water. Had weak gas blow on last two runs. SWIFN.
- 01/12/05 Had 450 psi on tubing. Opened up to test tank & bled gas off with no fluid. Rigged up swab. Had fluid @8400' from the surface on first run. On third run had fluid @10,500' from the surface. Lost No-Go & swab cups in the tubing. Ordered out BOP. Will pull tubing in the morning. SWIFN.
- 01/13/05 Rigged up pump truck & loaded tubing with 35 bbls of 10#/gal brine water. Nipple down tree. NUBOP. Unset packer. Pulled out of the hole with tubing & packer. Found No-Go in bottom profile nipple but did not find cups. Rubber on the packer was damaged & will have to be redressed. In the morning we'll run back & chase pipe until cups are found. SWIFN.

ALPHA "7" NO. 2

Sec. 7, T-15-S, R-34-E Lea County, New Mexico

DAILY COMPLETION REPORT

01/14/05 Ran in the hole with packer & tubing. Found cups in 24th stand. Set packer @13,428' & re-entry guide @13,438'. Tested packer good to 2000 psi. NDBOP. Nipple up tree. Tested seal good to 8000 psi. Hooked flowline up to test tank. SWIFN.

TUBING DETAIL	
436 – jts 2-7/8" L80 6.50# tubing	13,400.55'
1 – On-off tool	1.44'
1 – 2-7/8" x 2.313" X profile nipple	.66'
1 – 5-1/2" x 2-7/8" ASIX 10K (packer)	7.14'
1 - 2-7/8" N80 sub	10.65'
1 – 2-7/8" x 2.313" XN profile nipple	.66'
1 - 2 - 7/8" re-entry guide	.43'
KB adjustment	<u> </u>
	13,438.47'

- 01/15/05 Began swabbing. First run fluid was @900' from the surface. Swabbed down to 11,800' from surface. Recovered 79 bbls of brine water with no oil. Had weak gas show on last 3 runs. Shut well in until Monday morning. Will treat well Monday afternoon or Tuesday morning.
- 01/17/05 600 psi on tubing. Bled gas off, no fluid. Had fluid level @4800' from the surface on the first run. Swabbed down to 11,300'. Recovered a total of 43 bbls of water, had weak gas show. SWIFN.
- 01/18/05 400 psi on tubing. Flowed down to test tank. Rigged up & began swabbing to tank. First run fluid level @8300'. Swabbed down to 11,500', recovered 14 bbls of water. Rigged up Halliburton & treated w/2000 gals of Clay-safe acid & 60 ball sealers. Displaced w/80 bbls of 6% KCL water. Broke down @5000 psi. Average treating pressure @5600 psi @4.5 bpm. Did not see any ball action. ISIP 4343 psi, 5 min 3683 psi, 10 min 2817 psi, 15 min 2264 psi. Rigged down Halliburton. Hooked well up to test tank. Had 1300 psi on tubing. Flowed down to 0 pressure in 1 minute. Rigged up & began swabbing. Made 15 runs, fluid level down to 5100' from surface. Recovered 71 bbls of fluid, total load is 143 bbls. SWIFN.

ALPHA "7" NO. 2

Sec. 7, T-15-S, R-34-E Lea County, New Mexico

DAILY COMPLETION REPORT

- 01/19/05 50 psi on tubing. Fluid level on first swab run was at 1200' from the surface. Found damaged sandline at 6000'. Stopped swabbing & shut well in. Recovered 37 bbls of acid water. Recovered 108 bbls of 143 bbl load. Will replace sandline in the morning & continue swabbing.
- 01/20/05 700 psi on tubing. First run, fluid level @4000'. Swabbed down to 8000'. Recovered 50 bbls of water. Recovered a total of 158 bbls after acid job, load was 143. Have very little gas while swabbing. SWIFN.
- 01/21/05 550 psi on tubing. Fluid level @5700' on first run. Swabbed down to 11,100', recovered 49 bbls of water. Making a small amount of gas. Rigged down swab. Rigged up pump truck. Loaded tubing with 65 bbls of brine water. Nippled down tree & nippled up BOP. Unset packer & started out of the hole with tubing & packer. SWIFN.
- 01/24/05 200 psi on tubing. Pulled out of the hole with tubing. Laid down packer. Rigged up wireline truck & ran in the hole with 4.65" gauge ring to 13,600'. Picked up cast iron cement retainer & set @13,566'. Rigged down wireline truck. Ran in hole to 6500' with tubing. SWIFN.
- 01/25/05 0 psi on tubing & casing. Finished running in the hole with tubing & stinger. Rigged up Halliburton to squeeze lower perfs (13,584-93') with 75 sx of "H" cement. Broke circulation & loaded hole with 10# brine water. Stung into retainer. Pressured up on casing to 1000 psi & held. Bled pressure off & opened casing valve to the pit. Bullheaded brine water in tubing into formation at rate of 2 bpm @3800 psi. Back side stayed dead. Pressure increased to 4500 psi with cement in formation. Stopped pumping, had 4000 psi on tubing. Pulled out of retainer. Reversed out. Had ±1 bbl of cement to pit. Rigged down Halliburton & started out of the hole with tubing. Shut down due to high winds.
- 01/26/05 Tubing pressure 0 psi. Finished pulling out of the hole with tubing & stinger. Picked up packer & ran back in hole. Set packer @13,426'. SWIFN.
- 01/27/05 Tubing pressure 0 psi. Rigged up pump truck & tested packer to 2000 psi & held. NDBOP. Nippled up tree, tested good to 8000 psi on seal. Began swabbing. Swabbed down to 11,500' & pulled from 12,300' on last run. Had a very small amount of gas on last run. Recovered a total of 78 bbls of 10#/gal brine water. SWIFN.

ALPHA "7" NO. 2

Sec. 7, T-15-S, R-34-E Lea County, New Mexico

DAILY COMPLETION REPORT

- 01/28/05 Tubing pressure 0 psi. Fluid level @7500' on first run. Swabbed down to 12,000' from surface. Recovered 26 bbl of salt water. Rigged up Halliburton & treated with 1500 gallons of Claysafe "H" acid & 50 ball sealers. Formation broke down @4200 psi. Treated @5150 psi & rate of 3.6 bpm. ISIP 4650 psi, 5 min 4279 psi, 10 min 3864 psi & 15 min 3259 psi. Flowed down to test tank. Rigged up & began swabbing to test tank. Swabbed down to 5700' from surface. Recovered 70 bbls of KCL water with no gas. SWIFN. Load from acid job is 125 bbls.
- 01/29/05 Tubing pressure 0 psi. Fluid level @1900' from surface. Continued swabbing. Swabbed down to 8900' from the surface. Recovered a total of 85 bbls for the day. Load from the acid job was 125 bbls. Swabbed back a total of 155 bbls after acid treatment. On last 5 runs swabbing back salt water with a weak gas blow. Shut well in until Monday a.m. Will check pressure & make a swab run first thing & shut down to change out tubing line on rig.
- 01/31/05 850 psi on tubing. Fluid level @4700'. Changed out tubing line on pulling unit. Loaded tubing with 10#/gal brine water. Nippled down tree. NUBOP. Unset packer. Laid down 32 joints. SWIFN.
- 02/01/05 0 psi on tubing. Pulled out of the hole with tubing. Laid down packer. Rigged up wireline truck. Ran in the hole with CIBP & set @13,470'. Dumped 20' of cement on top of plug. Rigged down wireline truck. SWIFN.
- 02/02/05 Rigged up wireline truck. Ran in the hole with casing gun & perforated Atoka @12,551-62', 4 spf. Rigged down wireline truck. Ran back in the hole with tubing & packer. Set packer @12,476'. Rigged up pump truck & tested packer good to 2000 psi. NDBOP. Nipple up tree. Tested seal, good to 8000 psi. SWIFN.

TUBING DETAIL

- 405 jts 2-7/8" L80 6.50# tubing
 - 1 On/off tool
 - 1 2.313" X nipple
 - 1 Arrowset 10K packer @12,476'
 - 1 2 7/8" x 10' sub
 - 1 2.313" XN nipple
 - 1 wireline re-entry guide @12,487'

ALPHA "7" NO. 2

Sec. 7, T-15-S, R-34-E Lea County, New Mexico

DAILY COMPLETION REPORT

- 021/03/05 Tubing pressure 0 psi. Fluid level @1300' from the surface. Swabbed down to 11,900'. Recovered 64 bbls of brine water, had a slight gas show. SWIFN. Will acidize in the morning.
- 02/04/05 Tubing pressure 0 psi. Fluid level @11,500' from surface. Rigged up Halliburton & treated with 1500 gals of Claysafe "H" acid & 50 ball sealers. Formation broke down @5060 psi. Treating rate & pressure 4 bbl/min @4200 psi. Displaced with 74 bbls of 6% KCL water. ISIP 3068, 5 min 2932 psi, 10 min 2848 psi & 15 min 2781 psi. Turned to test tank & bled pressure off. Began swabbing. Swabbed down to 10,700'. Recovered 83 bbls of water, no gas. Load is 110 bbls. SWIFN.
- 02/07/05 Tubing pressure 0 psi. Fluid level @7500' from surface. Rigged up pump truck & loaded tubing with 40 bbls of brine water. Nippled down tree. NUBOP. Unset packer. Laid down 85 joints of tubing. Stood back 320 joints & laid down packer. SWIFN.
- 02/08/05 Rigged up wireline truck. Ran in hole & set CIBP-@12,500'. Dumped 20' cement on top of plug. Ran in hole with casing gun & perforated (9978-84'), (10,129-35') & (10,173-78') 4 spf. Rigged down wireline truck. Picked up packer & ran in the hole with tubing to 10,187'. SWIFN. Will acidize in the morning.
- 0/20905 Tubing & casing on slight vacuum. Rigged up Halliburton. Broke circulation with brine water. Spotted 300 gals of 15% NeFe HCL acid across perforations. Moved packer to 9809' & set. Pressured up to 500 psi on casing & packer. Treated with 3200 gals of 15% NeFe HCL & 120 ball sealers. Average rate & pressure was 4.5 bpm @6600 psi. Had good ball action. Balled out with 10 bbls of flush left to go. Shut down & surged off balls. Continued flush. ISIP 4953 psi, 5 min 4640 psi, 10 min 4495 psi & 15 min 4398 psi. Flowed down to test tank. Swabbed down to 4000' from the surface. Recovered 87 bbls of fluid. SWIFN.
- 02/10/05 Tubing pressure 300 psi. Fluid level @2500' from the surface. Had a trace of oil on the first run. Continued swabbing. From 8:30 a.m. to 3:30 p.m. swabbed back 59 bbls of fluid, 10% oil cut on last few runs. Fluid level @packer (9800'). From 3:30 p.m. to 6:00 p.m. had 6 bbls of fluid entry, 15% oil cut. Had some gas. Recovered 152 bbls of 207 bbl load. SWIFN.

ALPHA "7" NO. 2

Sec. 7, T-15-S, R-34-E Lea County, New Mexico

DAILY COMPLETION REPORT

- 02/11/05 Had 0 psi on tubing. Fluid level at 7700' from the surface. Had 600' of free oil on first run. Pulled from packer on 2nd run, oil cut was 15%. Shut down & waited 2 hours. Made swab run. Fluid at 8900' from the surface, had 1000' of fluid. Shut down & waited 2 hours. Made another swab run. Fluid level at 8900', oil cut 15%. Shut well in. Recovered 8 bbls of fluid.
- 02/14/05 Tubing pressure 70 psi. Fluid level at 6500' from the surface, 90% oil. NDBOP. Rigged down pulling unit. Left well shut in.

TUBING DETAIL

. .

- 318 jts 2-7/8" L80 6.50#/ft tubing
 - 1 5-1/2" x 2-7/8" X2.313" X nipple & on/off tool
 - 1 5-1/2" x 2-7/8" AS-1X 10K pkr @9809'
 - 1 2-7/8" N80 Pup jt (10')
 - 1 2-7/8" x 2.313 XN nipple
 - 1 2 7/8" wireline entry guide @9819'

PATTERSON PETROLEUM LP

