Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
1301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION	<u>30-025-36859</u> 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505District IV	
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 34275
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Saunders Deep State
1. Type of Well: Oil Well X Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
Energen Resources Corporation	162928
3. Address of Operator 3300 N. A. St., Bldg. 4, Ste. 100 Midland, TX 79705	10. Pool name or Wildcat Wildcat
4. Well Location	WIIUcat
Unit Letter A/Lot 1 : 420 feet from the North line and	
Section 3 Township 15-S Range 33-E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, e 4192'	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well D	istance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construct	
NOTICE OF INTENTION TO: SUE	, Report, or Other Data 3SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	ABANDONMENT
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	ABANDONMENT
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB   OTHER: OTHER: OTHER:	SSEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB	ALTERING CASING
NOTICE OF INTENTION TO: SUB   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB   OTHER: OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact	ALTERING CASING ALTERING CASING ING OPNS. PLUG AND ABANDONMENT SEC Ve pertinent dates, including estimated date h wellbore diagram of proposed completion 417' set @ 413'. Cemented w/800 L, welded on 13-3/8"X13-5/8" 3M# SOW
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CASING TEST AND COMPLETION CASING TEST AND CASING TEST AND COMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: CASING TEST AND CASING TEST AND COMENT JOB   OTHER: OTHER: OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OTHER:   14. Spud-17-1/2" hole @ 11:45 p.m. on 2/27/05 Reached TD of 413' in surface casing @ 9:30 a.m. 2/28/05 3. Ran a total of 9 jts 13/-3/8" H-40 48# ST&C R-3 casing totaling sacks of Class "C" cement. Total slurry was 1088 cu. ft.   4. Circulated 239 sacks to reserve. WOC 9 hrs., cut-off csg 37" BG head and test to 600#. NJU BOP. Drilling ahead. Drilling ahead.   5. TD'd the 12/-1/4" hole @ 5870' @ 9:30 a.m. 3/19/05. Run 9-5/8"   hereby certify that the information above is true and complete to the best of my knowledge	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDONMENT SECONDECTON ABANDON ABANDONMENT SECONDECTON ABANDON
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB   OTHER: OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.   1. Spud 17-1/2" hole @ 11:45 p.m. on 2/27/05   2. Reached TD of 413' in surface casing @ 9:30 a.m. 2/28/05   3. Ran a total of 9 jts 13/-3/8" H-40 48# ST&C R-3 casing totaling sacks of Class "C" cement. Total slurry was 1088 cu. ft.   4. Circulated 239 sacks to reserve. WOC 9 hrs., cut-off csg 37" BG head and test to 600#. NJU BOP. Drilling ahead.   5. TD'd the 12/-1/4" hole @ 5870' @ 9:30 a.m. 3/19/05. Run 9-5/8"   Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been will be constructed or closed according to NMOCD guidelines [X], a general permit	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDON
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB   OTHER: OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertiment details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OTHER:   14. Spud-17-1/2" hole @ 11:45 p.m. on 2/27/05 Reached TD of 413' in surface casing @ 9:30 a.m. 2/28/05 A.m. 2/28/05   3. Ran a total of 9 jts 13/-3/8" H-40 48# ST&C R-3 casing totaling sacks of Class "C" cement. Total slurry was 1088 cu. ft. 4. Circulated 239 sacks to reserve. WOC 9 hrs., cut-off csg 37" BG head and test to 600#. NJU BOP. Drilling ahead. Drilling ahead.   5. TD'd the 12/-1/4" hole @ 5870' @ 9:30 a.m. 3/19/05. Run 9-5/8" Hereby certify the the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines [X], a general permit SIGNATURE MMM	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDON AB
NOTICE OF INTENTION TO: SUE   PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK   TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL   PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB   OTHER: OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OTHER:   14. Spud-17-1/2" hole @ 11:45 p.m. on 2/27/05 Reached TD of 413' in surface casing @ 9:30 a.m. 2/28/05 3. Ran a total of 9 jts 13/-3/8" H-40 48# ST&C R-3 casing totaling sacks of Class "C" cement. Total slurry was 1088 cu. ft.   4. Circulated 239 sacks to reserve. WOC 9 hrs., cut-off csg 37" BG head and test to 600#. NJU BOP. Drilling ahead. 5. TD'd the 12/-1/4" hole @ 5870' @ 9:30 a.m. 3/19/05. Run 9-5/8"   Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines [X], a general permit SIGNATURE MMM	ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT Set @ 413'. Cemented date h wellbore diagram of proposed completion 417' set @ 413'. Cemented w/800 L, welded on 13-3/8"X13-5/8" 3M# SOW casing. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan [ ory Analyst