Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

LC032450B

SUNDRY NOTICES AND REPORTS ON WELLS JUN 1 5 2011 Do not use this form for proposals to drill or to re-enter an

ľ			
1			

6. If Indian, Allottee or Tribe Name

abandoned well. Use For	III 3160-3 (APD) 101	such proposals.	3 6		
SUBMIT IN TRIPLICATE -	Other instructions	on reverse side		7. If Unit or	CA/Agreement, Name and/or No
Type of Well Oil Well				8. Well Nam	<u>Vnit WM 71037B</u> e and No. tix Unit #4
 Name of Operator Occidental Permian Limited Partners Address 	hip	157 3b Phone No. (<i>unclude ar</i>	7984	Federal 9. API Well	No.
P.O. Box 50250, Midland, TX 79710- 4. Location of Well (Footage, Sec., T., R., M., or Survey I 1980 FNL 1980 FWL SENW(F) Sec 15	Description)	432-685-5717	ea coae)		Pool, or Exploratory Area per Paddock (Gas)
				Lea	r Parish, State
12. CHECK APPROPRIATE TYPE OF SUBMISSION	BOX(ES) TO INC		NOTICE, REP	ORT, OR OT	HER DATA
Notice of Intent X Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation X Recomplet	te ly Abandon	Water Shut-Off Well Integrity Other
3 Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be perfollowing completion of the involved operations. I testing has been completed. Final Abandonment N determined that the final site is ready for final inspe	lete horizontally, give so formed or provide the E f the operation results or Notices shall be filed on	ubsurface locations and meas Bond No. on file with BLM/I La multiple completion or re	sured and true ver BIA Required succession are	tical depths of a ubsequent report new interval a F	all pertinent markers and zones. ts shall be filed within 30 days form 3160-4 shall be filed once

8/26-10/13/10 - RIH & tag @ 7281', clean & drill out to 9710'. Perf McKee @ 9303-9318, 9430-9460' Total 94 holes, acidize w/ 3855g 10% acid, swab. Frac w/ 6276g Wtr Frac GR27 + 61630g Delta Frac 200-R27 w/ 129450# sand, swab, pump and test.

12/11-12/30/10 - POOH w/ rods, punp & tbg. RIH & set CIBP @ 9250', dump bail 35' cmt, PBTD-9215'. RIH & set CIBP @ 9250', dump bail 35' cmt, PBTD-9215'. set CIBP @ 7175', dump bail 35' cmt, PBTD 7140'. Perf 6374-6398, 6402-6444' Total 56 holes. Acidize w/4000g 15% HCl acid, swab, pump and test.

2/22-2/28/11 - POOH w/ rods, pump & tbg, RIH w/ ESP and test.

4/1-4/6/11 - POOH w/ ESP, RIH & set CIBP @ 6320', SI well and wait for regualtory approval to P&A.

SETFN FOR REC	:ORD
	7
UN 5 2011	
JUN 3 ZUII	
REAU OF LAND MANAGEN	1 1ENT
t	KEAU OF LAND MANAGEN TO ARY-DEPARTMENT OF AGENCY ST