

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

CKC

Form C-103
May 27, 2004

HOBBS OCD

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

JUN 22 2011

WELL API NO.
30-025-06092

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
015824

7. Lease Name or Unit Agreement Name

Skaggs Grayburg Unit

8. Well Number 13

9. OGRID Number 003044

10. Pool name or Wildcat
Skaggs; Grayburg

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Burgundy Oil & Gas of New Mexico, Inc.

3. Address of Operator
401 W. Texas, Suite 1003 Midland, TX 79701

4. Well Location

Unit Letter B : 660 feet from the North line and 1980 feet from the East line
Section 13 Township 20 South Range 37 East NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3567' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: Return well to production ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Drill out CIBP @ 3610' & 40' of cmt on top
- 2) Cut over stuck TAC & fish out tbg below
- 3) Cement open hole 3775-3931 w/ 75 sx CI "C" cmt
- 4) Drill out cement to 3785'
- 5) Perf 3764-78 w/ 2JSPF
- 6) Acidize well w/ 1500 gal
- 7) Frac if warranted
- 8) Clean up hole & RIH w/ production equip
- 9) Potential

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Cindy K. Campbell TITLE Production Accountant DATE 06/17/2011

Type or print name Cindy K. Campbell E-mail address: CCampbell@t3wireless.com Telephone No. 432-684-4033

For State Use Only

APPROVED BY: Mark Whitaker TITLE Compliance Officer DATE JUN 22 2011

Conditions of Approval (if any):