State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	HARRE OCOIL C	ONSERVATION D	IVISION _		/
DISTRICT I 1625 N French Dr , Hobbs, NM 88240	MADDA AAS	1220 South St. Francis D Santa Fe, NM 87505	Or.	WELL API NO 30-025-07438	/
<u>DISTRICT II</u>	JUN 2 3 2011	Suittu I V, Titti O / O O O		5 Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 88210	JUN DO LON			STATE X	TEE T
DISTRICT III			<u> </u>	6 State Oil & Gas Lease No	
1000 Rio Brazos Rd, Aztec, NM 87410	RECEIVED				
	NOTICES AND REPO	RTS ON WELLS		7 Lease Name or Unit Agre	,
(DO NOT USE THIS FORM FOR				North Hobbs (G/SA) Un	nit 🗸
DIFFERENT RESERVOIR USE	E "APPLICATION FOR PER	MIT" (Form C-101) for such pro	oposals)	Section 29	
1 Type of Well Oil Well X	Gas Well	Other		8 Well No 231	/
2 Name of Operator	/- 9.50			9 OGRID No 157984	
Occidental Permian Ltd. 3 Address of Operator	/			10 Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City,	TX 79323			10 1 001 name of 11 nacat	110003 (0/3A)
4 Well Location	111 17525				
Unit Letter K 1650	Feet From The	West	2310 Feet F	From The South	Line \
Section 29	Township		ange 38-E	NMPM	Lea County
	11 Elevation (Show 3650' GL	whether DF, RKB, RT GR, etc.))		
Pit or Below-grade Tank Application	or Closure	<u> </u>			
Pit Type Depth of Gro		istance from nearest fresh w	ater well	Distance from nearest	surface water
Pit Liner Thickness mil		Volume bbls; (
THE Effet Thickness	DOTOW Grade Family				
	neck Appropriate Box to NTENTION TO:	o Indicate Nature of Notice		her Data EQUENT REPORT (OF:
PERFORM REMEDIAL WORK	7 PLUG AND ABAND	ON T REMEDIAL	WORK	ALTERII	NG CASING
TEN ONWINEMEDIAE WORK	_ ,	J,			
TEMPORARII V ARANDON	T CHANGE PLANS	COMMENC	F DRILLING OPNS	S PLUG 8	ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS		E DRILLING OPNS		& ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TE	E DRILLING OPNS ST AND CEMENT		ABANDONMENT
	Multiple Completion				& ABANDONMENT
PULL OR ALTER CASING OTHER: Clean out and acid trea 13. Describe Proposed or Completed	Multiple Completion at Operations (Clearly state	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11	Multiple Completion at Operations (Clearly state	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well.	Multiple Completion at Operations (Clearly state	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15	Multiple Completion at Operations (Clearly state 03. For Multiple Complet	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet) '' '' '' '' '' '' '' '' ''	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet) '' '' '' '' '' '' '' '' ''	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet) '' '' '' '' '' '' '' '' ''	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet) '' '' '' '' '' '' '' '' ''	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet) '' '' '' '' '' '' '' '' ''	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet) '' '' '' '' '' '' '' '' ''	CASING TE X OTHER: all pertinent details, and give	ST AND CEMENT	JOB	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet), 5% PAD acid. ment.	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra	ST AND CEMENT e pertinent dates, 1 am of proposed con	ncluding estimated date o	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet), 5% PAD acid. ment.	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra best of my knowledge and belief	e pertinent dates, i	ncluding estimated date ompletion or recompletion.	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet), 5% PAD acid. ment.	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra best of my knowledge and belief or an (atta	ST AND CEMENT e pertinent dates, 1 am of proposed con	ncluding estimated date ompletion or recompletion.	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet), 5% PAD acid. ment.	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra best of my knowledge and belief oermit or an (atta plan	e pertinent dates, 1 am of proposed con f I further certify the	ncluding estimated date ompletion or recompletion. at any pit or below-grade tan DCD-approved	f starting any
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet 05. 5% PAD acid. nent. e is true and complete to the nes, a general 1	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra best of my knowledge and belief permit or an (atta plan	e pertinent dates, i am of proposed con for for for formation of formation of formation of the formation of the formation of the formation of formation of formation of formation of the formatio	ncluding estimated date ompletion or recompletion. at any pit or below-grade tan DCD-approved ssociate DA	f starting any k has been/will be TE 06/22/2011
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet 05. 5% PAD acid. nent. e is true and complete to the nes, a general 1	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra best of my knowledge and belief or an (atta plan TITLE ail address: mendy job	e pertinent dates, 1 am of proposed con f I further certify the ached) alternative (Administrative A	at any pit or below-grade tan DCD-approved SSOCIATE DA TELEPHONE N	f starting any k has been/will be TE 06/22/2011
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production. I hereby certify that the information above constructed or closed according to NMOCD guideling SIGNATURE TYPE OR PRINT NAME Mendy A For State Use Only	Multiple Completion at Operations (Clearly state 03. For Multiple Complet 05. 5% PAD acid. nent. e is true and complete to the nes, a general 1	casing te x others: X	e pertinent dates, 1 am of proposed confirmed for a further certify the ached) alternative (Administrative Amson@oxy.com	at any pit or below-grade tan DCD-approved SSOCIATE TELEPHONE N	f starting any k has been/will be TE 06/22/2011 O. 806-592-6280
PULL OR ALTER CASING OTHER: Clean out and acid treat 13. Describe Proposed or Completed proposed work) SEE RULE 11 1. Kill well. 2. POOH w/ESP equipment. 3. Clean out well to PBTD @4250 4. Acid treat well w/2800 gal of 15 5. Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production.	Multiple Completion at Operations (Clearly state 03. For Multiple Complet 05. 5% PAD acid. nent. e is true and complete to the nes , a general part of the ne	CASING TE X OTHER: all pertinent details, and give ions: Attach wellbore diagra best of my knowledge and belief or an (atta plan TITLE ail address: mendy job	e pertinent dates, 1 am of proposed con f I further certify the ached) alternative (Administrative A	at any pit or below-grade tan DCD-approved SSOCIATE TELEPHONE N	f starting any k has been/will be TE 06/22/2011