Form 3160-5 (April 2004)

Notice of Intent

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCT-HOBBS

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
	5. Lease Serial No. NM-56749
	6. If Indian, Allottee or Tribe Name
_	7. If Unit or CA/Agreement, Name and/or No.
	8. Well Name and No. TEXACO FEDERAL COM. #2 9. API Well No.
	30-025-30943
	10. Field and Pool, or Exploratory Area
	11. County or Parish, State

Water Shut-Off

		tructions on reverse side.		
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.			
Type of Well Oil Well Name of Operator THREE RI	Gas Well X Other	SWD / CUII	8. Well Name and No. TEXACO FEDERAL COM. #2 9 API Well No.	
Sa radicos	AL OF TEXAS HWY. , TEXAS 78746	3b. Phone No. (include area code) 512-600-3196	30-025-30943 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., UNIT "G" 1980' I	11. County or Parish, State LEA CO. NEW MEXICO			
12. CHECK AI	PPROPRIATE BOX(ES) T	O INDICATE NATURE OF NOTICE, R	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION				

Alter Casing Well Integrity Fracture Treat Reclamation XX Other CLEAN OUT Casing Repair New Construction Recomplete XX Subsequent Report ACIDIZE Change Plans Temporarily Abandon Plug and Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection RUN MIT 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

Deepen

Production (Start/Resume)

determined that the site is ready for final inspection.) 1. Moved in and rigged up well service unit

Acidize

- 2. Nippled down wellhead, installed B.O.P.
- 3. Released packer and came out of hole with thbing and packer.
- 4. Went back in hole with workstring bit and scraper cleaned out to top of CIBP @ 7960'
- 5. Circulated hole clean and came outrof hole, went back in hole with packer and tubing, set packer at 6170'. Pressure up an annalus to 500 PSI, acidized well with 2000 Gal 15% HCL, flowed back load.
- 6. Rigged up pump truck pressured up on casing to take MIT 30min test no pressure decrease. Rigged down pump truck and released
- 7. Cleaned location FRw 5/05/14/11

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)						- 4			
Joe T. Janiga	Title	Permit	Eng.						
Signature of Jamie	Date	06/	03/00	EPT	ED FO	OR REC	ORD		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved by		Title		JĮ	M 2 1	2011			
Conditions of approval, if any, are attached. Approval of this notice does not warrancerufy that the applicant holds legal or equitable to those rights in the subject lewhich would entitle the applicant to conduct operations the conduct of the co		Office	RIJE	FALLO)F LAND	MANAGEM	FNT		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person r within	knowingly and wi	Ifully to mai	@/to? [ati	y3departino	epti (Di (O E dep (ed) Fo	f the United		

