Submit 3 Copies To Appropriate District Office State of New Mexico Office Financy Mingrals and Network Programs	Form C-103 June 19, 2008
Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avc., Artesia, NM 88210 District III 1220 South St. Francis Dr.	WELL API NO. /
District II 1301 W. Grand Ave., Artesia, NM 88210 TOUBS OF CONSERVATION DIVISION	30-025-40065
District III 1000 Rio Brazos Rd, Aztec, NM 874JUN 0 8 2011 Santa Fe. NM 87505	5. Indicate Type of Lease STATE ☐ FEE ☒
District 1V	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fc, NM 87505	
SUNDRY NOTICE OF REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Turner
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	8. Well Number 010
Type of Well: ☑Oil Well ☐ Gas Well ☐ Other: 2. Name of Operator /	9. OGRID Number /
Apache Corporation	873 Number
3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705	Blinebry O&G(Oil)6660/Tubb O&G(Oil)60240
4. Well Location Unit Letter O: 467 feet from the South line and 13	332 feet from the East line
Section 29 Township 21S Range 37E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, et	
3464' GL	2 30 E X 3
12. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	NT JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER: Compl	- P
13. Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
	and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows:	and give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59',
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 55.
 Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 	Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', Glush w/4704 gal linear gel. RIH & set CBP @
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 55. Sc. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62',
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 55. Sc. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62',
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 55. Sc. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62',
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 58. Glush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP Spud Date: 02/27/2011 Rig Release Date: 03/08/2011	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 58. Glush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81', 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP Spud Date: 02/27/2011 Rig Release Date: 03/08/2011	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 58. Glush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 87' 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP Spud Date: 02/27/2011 Rig Release Date: 03/08/2011 Thereby certify that the information above is true and complete to the best of my knowled.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 3. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40 dge and belief. DATE 06/06/2011
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 15850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 81' 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP Spud Date: 02/27/2011 Rig Release Date: 03/08/2011 Thereby certify that the information above is true and complete to the best of my knowled.	Attach wellbore diagram of proposed completion D @ 6500'. Circ clean , 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. flush w/4704 gal linear gel. RIH & set CBP @ 1', 5612', 17', 20', 26', 31', 35', 41', 50', 56', 62', 52 gal acid; 28,266 gal SS-25; 62,534# 20/40 DATE
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Apache completed this well, as follows: 3/22/2011 MIRUSU. PU DC's & Tbg 3/23/2011 Tag cement @ 3900'. DO cmt to DV tool @ 4005' - DO DV tool. Tag PBT 3/24/2011 Log; TOC @ 100'. Perf Tubb @ 6039', 41', 45', 89', 94', 99', 6101', 08', 12' 61', 65', 67', 73', 75', 77', 82', 88', 91', 93', 6209', 11', 29' w/2 SPF, 66 holes 3/25/2011 Acidize Tubb w/3000 gal HCL. 3/28/2011 Frac Tubb w/56,544 gal SS-25; 150,973# 20/40 sand; spot 1050 gal acid, 1 5850'. Perf Blinebry @ 5507', 16', 27', 31', 33', 35', 39', 41', 65', 67', 79', 87' 77', 95', 5703', 14', 16', 36', 38', 40' w/2 SPF, 60 holes. Frac Blinebry w/23 sand, flush w/5208 gal linear gel. 3/29/2011 CO & DO CBP @ 5850'. CO to PBTD @ 6499'. Circ clean. 3/30/2011 RIH w/prod equip. 3/31/2011 Set 640 Pumping Unit & POP Spud Date: 02/27/2011 Rig Release Date: 03/08/2011 Title Sr. Engr Tech Type or print name Reesa Holland E-mail address: Reesa.Holland@a	Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 1, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 2, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 2, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 2, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 2, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53. Attach wellbore diagram of proposed completion D @ 6500'. Circ clean 2, 16', 21', 23', 25', 27', 33', 35', 51', 53', 57', 59', 53', 57', 59', 53', 57', 59', 53', 57', 59', 53', 57', 59', 53', 57', 59', 53', 51', 50', 56', 62', 52', 52', 52', 52', 52', 52', 52', 5