HOBBS OCD

Form 3160-5 (September 2001)	UNITEL [,] STATES DEPARTMENT OF THE INTERIO		TORM APPROVED OM B No. 1004-0135 Expires January 31, 2004
SI	BURFAU OF LAND MANAGEMENT INDRY NOTICES AND REPORTS (5 Lease Serial No
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7 If Unit or CA/Agreement, Name and/or No
1 Type of Well On Well O Gas Well O Klother The Lechier			8. Well Name and No.
2 Name of Operator McDonnold Operating. Inc.			9 API Well No
3a Address 505 N. Big Spring Sulfe 204 3b Phone No (melude area code) Midland Tx 29781 432-682-3455			30 - 025 - 1174 10 Hield and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T. R., M., or Survey Description)			Langlie Mattix - Trirs an GB
	and 1980'FEL		11 County or Parish. State
	45-37E		Lea G. NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION			
	Acidize Deepen Production (Start/Resume) Water Shu-Off		
Notice of Intent	Alter Casing		Well Integrity
Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon			
Final Abandonment Notice Convert to Injustion Plug Back Water Disposal			
Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) ESTI moded date to Start WOrk is 8-15-11			
1. MIRU PEAFIG			
2. POOH w/ that PKR.			
3. Spot 50.5x plug from 2850-3050'.			
3. Spot 50 sx plug from 2850-3050'. 4 Load hole w/ mud laden fluid.			
S. Spot 255x plug from 1175'-1275'. las plus.			
6. Spot 255x plug from 340' - 440.			
8. Cut off anchors & install dry hole marker, Accepted for Record Only			
8. Cut aff anchors & Install dry hole marker, Accepted for Record Only 14 Thereby certify that the foregoing is true and correct			
Name (Printed/1)	(me Do anold	Title Provident	A CG FO-COT
Signature	MA MA	Viestaen	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
			<u></u>
Approved by		Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			
Intle 18 USC Section 1001 and Title 43 USC Section 121/, inake it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction			
(Instructions on mage 2)			

•

(Instructions on page 2)

Before LANglee JACK UNII "4 API# 30-025-11174 c 10 3/4" 32.75# @ 389! CmT w/ 225 SX. CMT Circ. BAKER AD-1 7" PKR @ 3238'. 7/6/2011 7" 13" @ 3293'. cmT w/ gousx. cmT Circ. TD 3595'



$$IO SX @ Surf.$$

$$IO SU @ Surf.$$

$$IO SU @ Surf.$$

$$IO SU & Surf$$