

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87801  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-11174</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> <b>Fed</b>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Langlie Jack Unit</b>
8. Well Number <b>4</b>
9. OGRID Number <b>14372</b>
10. Pool name or Wildcat <b>Langlie Mattix, 7rrrsQNB</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <b>Injection</b>
2. Name of Operator <b>McDonnold Operating, Inc.</b>
3. Address of Operator <b>SOS N. Big Spring Suite 204 Midland Tx 79701</b>
4. Well Location Unit Letter <b>B</b> : <b>660</b> feet from the <b>N</b> line and <b>1980</b> feet from the <b>E</b> line Section <b>20</b> Township <b>24S</b> Range <b>37E</b> NMPM <b>Lea</b> County <b>NM</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. **Estimated date to start work is 8-15-11.**

1. MIRU P&A Rig.
2. Set CIBP @ 3250'. Spot 25 sx cmt on top of plug. Load hole w/ 12.5#/gal mud laden fluid.
3. Spot 25 sx plug from 2800'-2900'.
4. Perf SQZ holes @ 1275'. SQZ 35 sx cmt. WOC & tag plug.
5. Perf SQZ holes @ 440'. Fill 10 3/4' & 7" CSG w/ 175 sx Cmt.
6. Cut off anchors & install dry hole marker.

Accepted for Record Only

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. M. McDonnold TITLE President DATE 6-2-11  
Type or print name Praig M. McDonnold E-mail address: \_\_\_\_\_ PHONE: 432-682-3499  
**For State Use Only**

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of Approval (if any):