

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

HOBBS OED

JUL 05 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

WELL API NO. 30-025-24814
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A-16
8. Well Number 1
9. OGRID Number 14372
10. Pool name or Wildcat 7 rurs QN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
McDonnold Operating Inc.

3. Address of Operator
505 N. Big Spring Suite 204, Midland Tx 79701

4. Well Location
Unit Letter **m** : **Q330** feet from the **S** line and **660** feet from the **W** line
Section **16** Township **24S** Range **37E** NMPM **Lea** County **NM**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIREU P&A rig.
2. Spot 255x plug from 3450'-3350'. WOC - TAG
3. Load hole w/ 12.5#/gal mud laden fluid.
4. Spot 255x plug 1300'-1200'. WOC and tag plug.
5. Perf 502 holes @ 460' + fill CSG w/ cmt.
6. Cut off anchors + install dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Craig M. McDonnold TITLE President DATE 7-1-11
Type or print name Craig M. McDonnold E-mail address: _____ PHONE: 432-682-3499
For State Use Only

APPROVED BY [Signature] TITLE State Manager DATE 7-6-2011
Conditions of Approval (if any): _____

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS

State A-16 #1
API # 30-025-24814

8 5/8" 20# @ 410'. cmT
w/ 260 SX. TOC - Circ To Surf.

□ CSG LK 1145-1272'.
Pmp 400 SX + Circ cmT To
Surf. DO cmT. Would NOT Test.
Re-Sa2 w/ 100 SX. Tested CSG
To 300 PSI for 30 min. OK.

Perfs: 3456' - 3558'

5 1/2" 14# @ 3650'. cmT w/
300 SX. TOC @ 2450' by CBL.

AFTER

Fill $5\frac{1}{2}"$ + $8\frac{5}{8}"$ w/
CMT from 460' - Surf.

SQ2 holes @ 460' &

STATE A-16 #1

API # 30-025-24814

$8\frac{5}{8}"$ 20" @ 410'. CMT
w/ 260 SX. TOC - Circ To Surf.

CMT Plug
1300' - 1200'

CSG LK 1145-1272'.
Pmp 400 SX & Circ CMT To
Surf. DO CMT. Would NOT Test.
Re-SQ2 w/ 100 SX. Tested CSG
To 300 PSI. For 30 min. OK.

CMT Plug 3450' - 3350' /

Perfs: 3456' - 3558'.

$5\frac{1}{2}"$ 14" @ 3650'. CMT w/
300 SX. TOC @ 2450' by CBL.

