UNITED STATES OCD-HOBBS

Expires March 31, 2007	OM B No 1004-0137 Expires March 31, 2007
------------------------	---------------------------------------------

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

20r	BUREAU OF LAND MAN NOTICES AND REF	_LS	5. Lease Serial No. NMNM-036852	
RECEIVED not use the abandoned we	nis form for proposals t ell. Use Form 3160-3 (a	o drill or to re-e APD) for such pro	nter an posals.	6 If Indian, Allottee or Tribe Name
SUBMIT IN TR	7 If Unit or CA/Agreement, Name and/or No			
Type of Well Oil Well Name of Operator NADEL AND Address	8. Well Name and No. YOUNG DEEP 3 #4 9. API Well No. 30-025-28481			
PO BOX 1936 ~ ROSWELL		575/623/6601		10 Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., Sec. 3: T18S, R32E, SWSE, 12				YOUNG BONE SPRING, N. 11. County or Parish, State Lea, New Mexico
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYP	E OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of Statement of Statem	Well Integrity Other
If the proposal is to deepen dire Attach the Bond under which the following completion of the inv	ectionally or recomplete horizontall ne work will be performed or provi- volved operations If the operation nal Abandonment Notices shall be	y, give subsurface location de the Bond No on file w results in a multiple compl	is and measured and tru ith BLM/BIA Require letion or recompletion i	ny proposed work and approximate duration thereof the vertical depths of all pertinent markers and zones and subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has
BLM Bond No. NMB0005	20/Surety Bond No. B004230			
Cont TIH to 9158, push C Circulate Plugging mud. I 45 sx Cl H @10,045 (Tag@ POOH, LD tbg. Weld on I 4718, POOH laying down 3657 (Tag@3370). Spot 40	IBP to 10,747. Drill 10,747-11, FOOH, LD bit, TIH to 12,360, @9984). Spot 25 sx Cl H @9600 Pull nipple, rig up wire line. Rl csg. PU tbg and TIH, stopped	020. Spot 15 sx Cl H @ spot 45 sx Cl H @ 12,3 0 (Tag@9341). Spot 55 IH w/cutter, stopped @ 1 @ 5021, Call BLM-go Spot 35 sx Cl C @ 143) 10,884. WOC Tag (60, (Tag @ 11,986). sx Cl H @ 8863 (Ta (4718. Call Pam(BL) t ok. Spot 110 sx Cl	and TIH to 8329. DO CIBP @ 8324-8327. @ 10893, Drill 10,893-11,020. TIH to 12,500. Spot 45 sx Cl H @ 11,347(Tag@10,933). Spot g 8162). Spot 25 sx Cl C @ 6152 (Tag@5526). M), received OK to cut csg @ 4718. Cut csg C @ 5021 (Tag@4591). Spot 40 sx Cl C @ 30 sx Cl C @733(Tag@606). Spot 20 sx Cl C
	Lial	epted as to pluggin bility under bond is face restoration is 0	retained until	RECLAMATION DUE_/2~S~//

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Tammy R) Link Title Production Tech Signatur Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency for the United VI States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ARI SBAD FIFID OFFICE <u>CARLSBAD FIFLD OFFICE</u>

(Instructions on page 2)