

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Susana Martinez Governor

John H. Bemis Cabinet Secretary Jami Bailey
Division Director
Oil Conservation Division

& & Inspection Pengram
"Preserving the lengthy of Ow Environment"

21-Jul-11

ENERVEST OPERATING L.L.C.

1001 FANNIN STREET SUITE 800 HOUSTON TX 77002

**LETTER OF VIOLATION - Inspection** 

Dear Operator.

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

M S BERRYMAN No.001					O-11-21S-36E	30-025-04613-00-00	
Inspection Date	Type Inspection		Inspector	Violation?	* Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/20/2011	Routine/Peri	odie	Mark Whitaker	Yes	No	8/31/2011	1MAW1120222763
	Violations						
	Surface Damage	e/Restoration					
Comments on Inspection:		DO NOT RELEASE BOND. Rule 19.15.25.10 requires that location will be remediated within 1 year of plugging. Operator will need to remove transformers, fuses, conduit, and power disconnect from power pole. Also remove rod anchor on NE corner, concrete block on NW corner, polypipe					

year of plugging. Operator will need to remove transformers, fuses, conduit, and power disconnect from power pole. Also remove rod anchor on NE corner, concrete block on NW corner, polypipe and other debris on SW corner of location. Remove polyline from location to battery (line is currently connected to overflow on water tank). Please submit C103 for final inspection when work in complete. FIRST NOTICE OF VIOLATION

--

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977 \$0.44 07/21/11 Mailed From 88240

ENERVEST OPERATING LLC 1001 FANNIN ST, STE 800 HOUSTON, TX 77002