	State of New I	viexico	Form C-103
Office <u>District I</u>	Energy, Minerals and N	atural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 8824 District II	O HOBBS OCD	WEL	L API NO. 30-025-36933
1301 W. Grand Ave., Artesia, NM 88	210 OIL CONSERVATION	ON DIVISION 5. Inc	licate Type of Lease
District I 1625 N. French Dr., Hobbs, NM 88240  District II 1301 W. Grand Ave., Artesia, NM 88210  District III 1000 Rio Brazos Rd., Aztec, NM 8741 JUL 2 2 2011  District IV  Energy, Minerals and Natural Resources  CONSERVATION DIVISION  1220 South St. Francis Dr.  Santa Fe, NM 87505		rancis Dr.	STATE FEE X
District IV 1220 S. St. Francis Dr , Santa Fe, NM		8/505 6. Sta	ate Oil & Gas Lease No.
87505	RECENTE		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		LS 7. Le	ase Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		FOR SUCH T D F	Pope 35
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well Other	8. W	ell Number 1
2 Name of Operator		9. 00	GRID Number
Celero I	Energy II, LP		247128
3. Address of Operator 400 V Midla	V. Illinois, Ste. 1601 nd, TX 79701		ool name or Wildcat
4. Well Location		· ·	
Unit Letter B	: 810feet from theN	line and 1980	feet from the E line
Section 35	Township 14S	Range 37E NMP	M CountyLea
<b>建心</b> 学的现在分词	11. Elevation (Show whether I	OR, RKB, RT, GR, etc.)	1506 1200 250 150 150 150
	3810'		
12. Che	ck Appropriate Box to Indicate	Nature of Notice, Repor	t or Other Data
NOTICE OF	F INTENTION TO:	SUBSECI	JENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐	COMMENCE DRILLING	
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE			
OTHER: Return to production	X	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any propose	ed work). SEE RULE 19.15.7.14 NM		
of starting any propose proposed completion of	ed work). SEE RULE 19.15.7.14 NM or recompletion.		
of starting any propose proposed completion of the MIRU. POOH w/ produces	ed work). SEE RULE 19.15.7.14 NM or recompletion.		
of starting any propose proposed completion of the MIRU. POOH w/ production of the Recover pkr @ 11,808'.	ed work). SEE RULE 19.15.7.14 NM or recompletion.		
of starting any propose proposed completion of a MIRU. POOH w/ production of the proposed in t	ed work). SEE RULE 19.15.7.14 NM or recompletion. ction tbg. to 12,530'.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively	ed work). SEE RULE 19.15.7.14 NM or recompletion. ction tbg. to 12,530'. 0'. grown 12,030-12,520'.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion. ction tbg. to 12,530'. 0'. grown 12,030-12,520'.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.		
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.		
of starting any propose proposed completion of the proposed completion of the proposed completion of the proposed completion of the proposed complete of the proposed compl	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.	AC. For Multiple Completion	
of starting any propose proposed completion of 1. MIRU. POOH w/ production 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations;	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.	AC. For Multiple Completion	
of starting any propose proposed completion of the proposed completion of the proposed completion of the proposed completion of the proposed complete of the proposed compl	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.	AC. For Multiple Completion	
of starting any propose proposed completion of the proposed complete of the proposed com	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.	AC. For Multiple Completion  Date:	ns: Attach wellbore diagram of
of starting any propose proposed completion of the proposed complete of the proposed com	ed work). SEE RULE 19.15.7.14 NM or recompletion.  ction tbg.  to 12,530'.  to 12,530'.  from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.  Rig Release	AC. For Multiple Completion  Date:	ns: Attach wellbore diagram of
of starting any propose proposed completion of the proposed complete the proposed com	recompletion.  ction tbg.  co 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.  Rig Release	AC. For Multiple Completion  Date:  best of my knowledge and be	elief.
of starting any propose proposed completion of the proposed complete of the proposed com	recompletion.  ction tbg.  co 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.  Rig Release	AC. For Multiple Completion  Date:	ns: Attach wellbore diagram of
of starting any propose proposed completion of 1. MIRU. POOH w/ production of 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations; 7. RIH w/ productuion equi	recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.  Rig Release  tion above is true and complete to the	AC. For Multiple Completion  Date:  best of my knowledge and be	elief. DATE 07/21/2011
of starting any propose proposed completion of 1. MIRU. POOH w/ production of 1. Recover pkr @ 11,808'.  3. Make bit & scraper run to 4. RIH & set RBP @ 12,52  5. Perf Devonian selectively 6. Acdz new perforations; 7. RIH w/ productuion equitions of the production	recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.  Rig Release  tion above is true and complete to the	Date:  best of my knowledge and beaulatory Analyst	elief.  DATE 07/21/2011
of starting any propose proposed completion of 1. MIRU. POOH w/ production of 2. Recover pkr @ 11,808'. 3. Make bit & scraper run to 4. RIH & set RBP @ 12,52 5. Perf Devonian selectively 6. Acdz new perforations; 7. RIH w/ productuion equi	recompletion.  ction tbg.  o 12,530'.  o'.  y from 12,030-12,520'.  POOH w/ RBP.  p & return well to production.  Rig Release  tion above is true and complete to the	Date:  best of my knowledge and beaulatory Analyst	elief.  DATE 07/21/2011