HOBBS OCD

Form 3160-5 (February 2005)		UNITED STATES	nn unp	\$8 2011		ORM APROVED IB NO. 1004-0135	
、		J OF LAND MANAGEMENT ICES AND REPORTS ON WELL	004		EXPIR 5. Lease Serial No.	ES: March 31, 2007	
	Do not use this form	for proposals to drill or to re-en	iter an BEA	en/em	N N	MLC-061863-A	
		Form 3160-3 (APD) for such pr	roposais IKE	EIVED	6. If Indian, Allotte	e or Tribe Name	
	50	BMIT IN TRIPLICATE			7 Unit or CA Agr	ement Name and No.	
1a. Type of Well	Oil Well Gas	s Well	/			sement Name and No.	
					8 Well Name and	No.	
2. Name of Opera	tor N ENERGY PRODUCT					onyx 6 Federal 2H	
3. Address and Te		ION COMPANY, LP			9. API Well No.	539949	
	•	oma City, Ok 73102-8260	405-235-3611		10. Field and Poo		
4. Location of Wel	II (Report location cleari		Wildcat Bone Spring -				
200' FSL 990' FWL / M 6 T25S R32E /						ish State	
BHL D 330 FNL &					Lea	NM	
TYPE OS	12. CHECK SUBMISSION	APPROPRIATE BOX(s) TO IN		TICE, REPOR	RT, OR OTHER DA	TA	
			Deepen		n (Start/Resume)		
		Alter Casing	Fracture Treat	Reclamat		Water Shut-Off Well Integrity	
✓ Subsequent	t Report	Casing Repair	New Construction	Recomple		✓ Other Drilling	
Final Aband	Ionment Notice	Change Plans	Plug and Abandon	U Temporar	rily Abandon	Operations	
13 . Describe Proposed deepen directionally or re	or Completed Operations (Cla	early state all pertinent details, and give pe bsurface location and measured and true v	tinent dates including estimated a	tate of starting an	v proposod work and one	roximate duration thereof If the proposal	
the bond no on me with	BLIM/BIA Required subseque	nt reports shall be filed within 30 days folio	owing completion of the involved o	perations of the i	preration results in a mult	inte completion or recompletion in a now	
determined that the site is	s ready for final inspection)	een completed. Final Abandonment Notic	ces shall be filed only after all requi	irement, including	reclamation, have been	completed, and the operator has	
5/22/11 - MIRL	l Spud						
5/24/11 - 5/25/	11 - TD 17 1/2" hol	le @ 750'. RIH w/ 18 jts 1:	3 3/8" 48# H40 STC (csa & set (750'. RUBJ	& lead w/ 850 sx C_Yld	
1.75 cf/sx. 1 ail	w/ 250 sx C. Yld 1	.35 cf/sx. Circ 113 sx to s	surf. WOC. Test to 3	85 psi w/ n	itrogen, held go	od. NU BOP test to 3000	
psi H and 250	psi L, 10 mins, goo	d. Notified BLM test and o	cementina.				
5/29/11 - ID 1	2 1/4" hole @ 4355	5'. Test BOPs. RIH w/ 96	jts 9 5/8" 40# J55 LT	C csg & se	t @ 4352'. RIH	w/ centralizers every 4th	
Johnson on loc	3J & lead W/ 1150 §	sx C, Yld 1.04 cf/sx. Tail v	w/ 300 sx C, Yld 1.38	cf/sx. Circ	c 501 sx to surf.	WOC. Notified BLM, J.	
		50 L10 mins, good. Test c	sa 1500 nei 30 mine	and DV	Tool @ EDGE!		
6/5/11 - TD PH	I @ 8764'. TOOH :	for Caliper Log & Whipsto	ckrun. RUWI CH	G Set cm	1001 @ 5965 . t nlua w/ 425 sr	H VId 1 18 of/ex	
6/20/11 - 6/22/	11 - TD 8 3/4" hole	@ 13,256'. Notified BLM	CO 5 1/2" csg rams	& retest do	ors on BOP: 25	0 psi L & 3500 psi H 10	
mins, good.							
6/25/11 - RIH	w/ csg as follows: 1	7248.97' of 10 stage pkr p	lus 135 jts 17# HCP-	110 LTC 8	124 jts 17# P1	10 BTC & set @ 13,207'.	
Yld 1.37 cf/sx.	ETOC 2823'	ead w/ 235 sx C, Yld 2.88	3 ct/sx and tail w/ 200	sx POZ 6	0:40.		
	21002020						
\Box		1					
Signed	ne /	Name Title.	Judy A. Barnett X Regulatory Anal		Date	6/28/2011	
	leral or State Office use	-		y31		6/28/2011	
(This space joi Ted	ieral of State Office use		/				
Approved by Conditions of appro	wal if any:	ATTIE			Date		
Conditions of appro	Jval, ir alty.	1 - 0					
THE TOUS CONNET	oo i, makee it a chine let any p		acpartment or agency or the Onlied within its jurisdiction	а онисе5 блутины	, fictious or fraudulers se	atements or representations to any matter	
						· · · · · · · · · · · · · · · · · · ·	
		"See In	struction on Reverse Sic	le			
		# AA		3	MENTEN		
		ANARBS OCH			JUEF IEU	FOR RECORD	
		HOBBS OCD JUL 28 2011 RECEIVED					
		28 2011					
		JUL				2 4 2011	
			$ 1 \rho $				
RECEIVE					Himo		
				l	BURFAU OF LA	ND MANAGEMENT	
					CARLSBAD	FIELD OFFICE	
				L			
						V :	