

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88203
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

HOBBS OCD OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 04 2011

WELL API NO. 30-025-05564 05574
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Monument G/SA Unit: Blk 01
8. Well Number 14
9. OGRID Number 873
10. Pool name or Wildcat Eunice Monument G/SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3708' GR
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/>
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water <u>N/A</u>
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: drill out & add Plugs ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/19/11-----MIRU.

7/20/11-----Sit down @ 508'.

5-1/2"

7/21/11-----Drilled out cmt from 508' to 636'. Tagged 51/2" CIBP @ 3818'.

7/22/11-----Circ hole from 3818' w/mlf. Spot 30 sxs cmt disp to 3529'.

7/25/11-----Perf @ 2740' pkr @ 2231'. Pressure tested to 1500psi. Contact OCD advised to spot 30 sxs. Spot 30 sxs from 2800' Woc & tagged cmt plug @ 2537'. Perf @ 1450' sqz 50 sxs woc.

7/26/11-----Tag cmt plug @ 1208'. Perf @ 344' pumping into perfs @ 800^{psi} @ 142 bbl/min. Did not circ. Contact OCD Advised to spot 25 sxs from 577' then sqz 50 sxs & disp to 100' woc & tag cmt plug @ 85'. Perf @ 60' circ 20 Sxs cmt from 60' to surf.

7/27/11-----Cut off wellhead & anchors. Install dryhole marker.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.cmnr.state.nm.us/oed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Randall Minear TITLE P & A Supervisor (Basic Energy Services) DATE 7-29-11

Type or print name: Randall Minear E-mail address: _____ Telephone No. 432-563-3355

For State Use Only

APPROVED BY: Mark White TITLE Compliance Officer DATE 08-05-2011

Conditions of Approval (if any):