Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I (575) 202 (161	Energy, Minerals and Natural Reso	urces October 13, 2009
1625 N. French Dr., Hobbs, NM 8824 HOBBS (OCD	WELL API NO.
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVIS	ION 30-025-11705
Dist-i-4 111 (505) 224 (170	2011 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 874 16 L 1 9 District IV – (505) 476-3460	Santa Fe, NM 87505	STATE FEE S
1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 c, 14141 67 5,05,	6. State Oil & Gas Lease No. 307960
87505 RECEIVE		
SUNDRY NOTICES	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION"	IO DRILL OR TO DEEPEN OR PLUG BACK ' N FOR PERMIT" (FORM C-101) FOR SLICH	
PROPOSALS.)	TORTERIAL TORNES-101) TORBOCK	LANGLIE MATTIX QUEEN UNIT
1. Type of Well: Oil Well Gas	Well 🛛 Other 🔨 工~	8. Well Number: 035
2. Name of Operator	3	9. OGRID Number 269324
LINN OPERATING, INC. ON BEHAL	F OF SANDRIDGE UNTIL COO	
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUSTON	TDVAG 55000	10. Pool name or Wildcat
000 TRAVIS, SUITE 3100, HOUSTON,	, IEXAS //002	LANGLIE MATTIX;7 RVRS-Q-
4. Well Location		GRAYBURG
	Cont. Community St. 15	,
Unit Letter E; 2310	feet from theN line an	
Section 23	Township 25S Range	
	Elevation (Show whether DR, RKB, RT	GR, etc.)
Committee the Market of the Committee of		
10 01 1		
12. Check Appro	priate Box to Indicate Nature of	Notice, Report or Other Data
NOTICE OF INTEN	TION TO:	CUROCOUENT REPORT OF
		SUBSEQUENT REPORT OF:
· · · · · · · · · · · · · · · · · · ·	-	ALTERING CASING
		ENCE DRILLING OPNS: PAND A
DOWNHOLE COMMINGLE	CASING	G/CEMENT JOB
DOWN HOLE COMMINGEE		
OTHER: <return produc<="" td="" to=""><td>TION- 🖾 OTHER</td><td></td></return>	TION- 🖾 OTHER	
13. Describe proposed or completed of	operations. (Clearly state all pertinent	letails and give pertinent dates including estimated date
13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mu	letails and give pertinent dates including estimated date
13. Describe proposed or completed of	operations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mu	etails, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mu	letails and give pertinent dates including estimated date
13. Describe proposed or completed of starting any proposed work). S proposed completion or recompleted or recompleted or complete or recompleted or reco	operations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recomple	operations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recomple LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY, JE & J. F. & K. I. S.
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING IDENTEMPT TO SOUEEZE IT OFF	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recomple LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING IDENTEMPT TO SOUEEZE IT OFF	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY, JE & J. F. & K. I. S.
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT
13. Describe proposed or completed of starting any proposed work). So proposed completion or recompletion or recompletion of the proposed completion or recompletion of the proposed completion of recompletion of the proposed completion of the proposed or completed of the proposed completed of the proposed or completed of the proposed or completed of the proposed completion or recompletion of the proposed completion or recompletion or recompl	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of Apropriate Apropriate Condition of Apropriate Packer (Condition of Apropriate Packer).	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Suproposed completion or recompletion or recompletion of the starting any proposed completion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AND A STARTING AND	pperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). So proposed completion or recompletion or recompletion of the proposed completion or recompletion of the proposed completion of recompletion of the proposed completion of the proposed or completed of the proposed completed of the proposed or completed of the proposed or completed of the proposed completion or recompletion of the proposed completion or recompletion or recompl	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of Apropriate Apropriate Condition of Apropriate Packer (Condition of Apropriate Packer).	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of source of Leakoff which has resulted in and casing as necessary. If a leak is with cement. If the scope of the project
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion of starting any proposed work). Sproposed completion or recompletion of recompletion and proposed completion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AN CHANGES, LINN WILL SUBMIT A NE	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours Rig Release Date:	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT OF TURNING MIT Test & Chart prior of running MIT Test of running MIT Test.
13. Describe proposed or completed of starting any proposed work). So proposed completion or recompletion or recompletion of the proposed completion or recompletion of the proposed completion of recompletion of the proposed completion of the proposed or completed of the proposed completed of the proposed or completed of the proposed or completed of the proposed completion or recompletion of the proposed completion or recompletion or recompl	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours Rig Release Date:	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT OF TURNING MIT Test & Chart prior of running MIT Test of running MIT Test.
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion of starting any proposed work). Sproposed completion or recompletion of recompletion and proposed completion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AN CHANGES, LINN WILL SUBMIT A NE	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBING ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours Rig Release Date:	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT OF TURNING MIT Test & Chart prior of running MIT Test of running MIT Test.
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion of starting any proposed work). Sproposed completion or recompletion of recompletion and proposed completion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AN CHANGES, LINN WILL SUBMIT A NE	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mution. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours office 24 hours office 24 hours.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT CONTROL OF THE PROJECT OF THE PROJECT OF TURNING MIT Test & Chart Prior of running MI
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion of starting any proposed work). Sproposed completion or recompletion of recompletion of recompletion and a railed mit. Linn will inspect identified, Linn will isolate and Changes, Linn will submit a new Spud Date: I hereby certify that the information above Signature and Changes.	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mustion. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours office 24 hours office 24 hours office 24 hours.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT COVAL: Notify OCD Hobbs Chart Perior of running MIT Test & Chart Peri
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion or recompletion of starting any proposed work). Sproposed completion or recompletion of recompletion o	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mustion. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours office 24 hours office 24 hours office 24 hours.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT COVAL: Notify OCD Hobbs Chart Perior of running MIT Test & Chart Peri
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion or recompletion of the proposed completion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AN CHANGES, LINN WILL SUBMIT A NE Spud Date:	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mustion. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours office 24 hours office 24 hours office 24 hours.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT COVAL: Notify OCD Hobbs Chart Perior of running MIT Test & Chart Peri
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion. LINN PROPOSES TO MOVE A RIG ON A FAILED MIT. LINN WILL INSPECT IDENTIFIED, LINN WILL ISOLATE AN CHANGES, LINN WILL SUBMIT A NE Spud Date: I hereby certify that the information above SIGNATURE LIND CALLAHA Type or print name, TERRY B. CALLAHA For State Use Only	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mustion. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours office 24 hours office 24 hours office 24 hours.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT CONTROL OF THE PROJECT OF THE PROJECT OF TURNING MIT Test & Chart Prior of running MIT Test & Chart Prior of running MIT Test & Chart Prior of PHONE: 281-840-4272
13. Describe proposed or completed of starting any proposed work). Sproposed completion or recompletion or recompletion or recompletion of starting any proposed work). Sproposed completion or recompletion of recompletion o	Deperations. (Clearly state all pertinent of SEE RULE 19.15.7.14 NMAC. For Mustion. TO LOCATION TO IDENTIFY THE THE PACKER, INJECTION TUBINO ID ATTEMPT TO SQUEEZE IT OFF W NOI. Condition of APF Office 24 hours office 24 hours office 24 hours office 24 hours.	details, and give pertinent dates, including estimated date altiple Completions: Attach wellbore diagram of SOURCE OF LEAKOFF WHICH HAS RESULTED IN AND CASING AS NECESSARY. IF A LEAK IS WITH CEMENT. IF THE SCOPE OF THE PROJECT COVAL: Notify OCD Hobbs Chart Perior of running MIT Test & Chart Peri

. . .