lew Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

John H. Bemis Cabinet Secretary-Designate

Brett F. Woods, Ph. D. **Acting Cabinet Secretary** Jami Bailey Division Director **Oil Conservation Division**



Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

11-Aug-11

OXY USA INC. ATTN: DALTON DEAN P.O. BOX 50250 MIDLAND, TX 79710

OXY USA INC. ATTN: VAN BARTON 1502 W. COMMERCE DR. CARLSBAD, NM 88220

LETTER OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

TANKERSLEY No.003

30-025-22988-00-00

Approved TA Salt Water Disposal Well

F-30-9S-34E

11/14/2011

Test Date:

8/11/2011

Permitted Injection PSI:

Actual PSI:

Test Reason:

Annual IMIT

Test Result:

Repair Due:

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

FAILED BHT;***FAILED OVERALL STATE INSPECTION DUE TO PRIOR COMPLIANCE ISSUES HAVE NOT BEEN CORRECTED BY OPERATOR***.OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*****OPERATOR NEEDS TO CORRECT PROBLEM REGARDING SURFACE/INTERMEDIATE CASING. OPERATOR MUST 1) DIG OUT AND VERIFY SURFACE AND INTERMEDIATE STRINGS. 2) LABEL INTERMEDIATE AND SURFACE IF APPLICABLE; 3) CONTACT OCD DISTRICT I OFFICE SO A VISUAL INSPECTION CAN BE PERFORMED BY THE STATE OCD DISTRICT I OFFICE.



August 11, 2011 Page 2

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sinferely,

Hobbs OCD District Office

COMPLIANCE OFFICER

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



0 15H14150977 **\$0.44** 08/11/11 Mailed From 88240

US POSTAGE

OXY USA INC. ATTN: DALTON DEAN P.O. BOX 50250 MIDLAND, TX 79710

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977 BB VE SO L 44 O8/11/11 Mailed From 88240 SD

OXY USA INC. ATTN: VAN BARTON 1502 W. COMMERCE DR. CARLSBAD, NM 88220