30-025-

HOBBS OCD

AUG 10 2011

Hydrogen Sulfide Drilling Operations Plan HT 18 Federal No. 6 Cimarex Energy Co. of Colorado Lot 2, Section 18 T17S R32E, Lea County, NM

- 1 All Company and Contract personnel admitted on location must be trained by a qualified H₂S safety instructor to the following:
 - A. Characteristics of H₂S
 - B. Physical effects and hazards
 - C. Proper use of safety equipment and life support systems.
 - D. Principle and operation of H₂S detectors, warning system and briefing areas.
 - E. Evacuation procedure, routes and first aid.
 - F. Proper use of 30 minute pressure demand air pack.
- 2 H₂S Detection and Alarm Systems:
 - A. H₂S detectors and audio alarm system to be located at bell nipple, end of flow line (mud pit) and on derrick floor or doghouse.
- Windsock and/or wind streamers: 3
 - A. Windsock at mudpit area should be high enough to be visible.
 - B. Windsock at briefing area should be high enough to be visible.
- **Condition Flags and Signs:**
 - A. Warning sign on access road to location.
 - B. Flags to be displayed on sign at entrance to location. Green flag indicates normal safe condition. Yellow flag indicates potential pressure and danger. Red flag indicates danger (H₂S present in dangerous concentration). Only emergency personnel admitted to location.
- 5 Well control equipment:
 - A. See exhibit "E"
- 6 Communication:
 - A. While working under masks chalkboards will be used for communication.
 - B. Hand signals will be used where chalk board is inappropriate.
 - C. Two way radio will be used to communicate off location in case of emergency help is required. In most cases cellular telephones will be available at most drilling foreman's trailer or living quarters.
- 7 Drillstem Testing:

No DSTs or cores are planned at this time.

- 8 Drilling contractor supervisor will be required to be familiar with the effects H₂S has on tubular goods and other mechanical equipment.
- 9 If H₂S is encountered, mud system will be altered if necessary to maintain control of formation. A mud gas seperator will be brought into service along with H₂S scavengers if necessary.

Page 3A

H₂S Contingency Plan HT 18 Federal No. 6 Cimarex Energy Co. of Colorado Lot 2, Section 18 T17S R32E, Lea County, NM

Emergency Procedures

In the event of a release of gas containing H₂S, the first responder(s) must:

- \star Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- ★ Evacuate any public places encompassed by the 100 ppm ROE.
- \star Be equipped with H₂S monitors and air packs in order to control the release.
- ★ Use the "buddy system" to ensure no injuries occur during the response.
- ★ Take precautions to avoid personal injury during this operation.
- ★ Contact operator and/or local officials to aid in operation. See list of phone numbers attached.
- ★ Have received training in the:
 - ♦ Detection of H₂S, and
 - Measures for protection against the gas,
 - Equipment used for protection and emergency response.

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO₂). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally, the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas.

Characteristics of H₂S and SO₂

Common	Chemical	Specific	Threshold		Lethal
Name	Formula	Gravity	Limit	Hazardous Limit	Concentration
Hydrogen Sulfide	H₂S	1.189 Air=1	10 ppm	100 ppm/hr	600 ppm
Sulfur Dioxide	SO₂	2.21 Air=1	2 ppm	N/A	1000 ppm

Contacting Authorities

Cimarex Energy Co. of Colorado's personnel must liaise with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available including directions to site. The following call list of essential and potential responders has been prepared for use during a release. Cimarex Energy Co. of Colorado's response must be in coordination with the State of New Mexico's "Hazardous Materials Emergency Response Plan" (HMER).

Company Office

...

Cimarex Energy Co. of Colorado Co. Office and After-Hours Menu 800-969-4789

Key Personnel

Name	Title	Office		Mobile
Doug Park	Drilling Manager	432-620-1934		972-333-1407
Dee Smith	Drilling Super	432-620-1933	-	972-882-1010
Jim Evans	Drilling Super	432-620-1929		972-465-0564
Roy Shirley	Field Super	a a secon la tecció la tecció de tecció de tecció de tecció de tecció de		432-634-2136
Artesia		7 # 123 # 123 # 124 # 124 # 125 # 125 # 125 # 125 #		a a waa ki kaa ki maa ki maa k
[Ambulance		911		
State Police		575-746-2703		
City Police		575-746-2703		
Sheriff's Office		575-746-9888		
Fire Department	575-746-2701			
Local Emergency Planning Committee	575-746-2122			
New Mexico Oil Conservation Division	575-748-1283	9 AUT # AU		
Carlsbad		7 W 1227 W 1227 A 1227 W 1227 W 1227 W 1227 W 1227		
Ambulance	······································	911		
State Police	575-885-3137	•••		
City Police		575-885-2111		
Sheriff's Office		575-887-7551		
Fire Department		575-887-3798		
Local Emergency Planning Committee		575-887-6544		
US Bureau of Land Management		575-887-6544		
Santa Fe			• • =	- • • • • • •
New Mexico Emergency Response Commission (Sar	505-476-9600			
New Mexico Emergency Response Commission (Sar	505-827-9126			
New Mexico State Emergency Operations Center	505-476-9635			
National		19 Junio II Anto II		ay is includ it factor in factor in factor in factor i
National Emergency Response Center (Washington,	D.C.)	800-424-8802	, , _	
Medical		7 8 67 8 67 8 67 8 67 8 67 8 67 8 67 8	<i></i>	
Flight for Life - 4000 24th St.; Lubbock, TX	806-743-9911			
Aerocare - R3, Box 49F; Lubbock, TX	806-747-8923			
Med Flight Air Amb - 2301 Yale Blvd S.E., #D3; Albu	505-842-4433			
SB Air Med Service - 2505 Clark Carr Loop S.E.; Albu		505-842-4949		
Other		****		
Boots & Coots IWC	······································	800-256-9688	or	281-931-8884
Cudd Pressure Control		432-699-0139	or	432-563-3356
Halliburton	575-746-2757			
B.J. Services		575-746-3569		

Surface Use Plan HT 18 Federal No. 6 Cimarex Energy Co. of Colorado Lot 2, Section 18 T17S R32E, Lea County, NM

- 1. <u>Existing Roads</u>: Area maps, Exhibit "A" shows the proposed well site as staked. Exhibit "B" is a reproduction of Eddy Co. General Highway Map. Exhibit "C" is a reproduction of a USGS Topographic Map, and Exhibit "C-1" is a well site layout map, showing proposed road to location and existing road.
 - A. The maximum width of the driving surface will be 15.' The road will be crowned and ditched with a 2% slope from the tip of the crown to the edge of the driving surface. The ditches will be 1' deep with 3:1 slopes. The driving surface will be made of 6" rolled and compacted caliche.
 - B. From mile marker 142, go Northeast 0.6 miles to lease road. On lease road, go South 0.5 miles to well pad and proposed location.
- 2. Planned Access Roads: No new lease roads are proposed.
- 3. <u>Planned Pipelines and Electric Lines</u>: Lay surface oil/gas/water 4" SDR-7 poly pipe along lease road to existing HT Fed #5 battery as shown on Exhibit C/POD. Gas will be separated at battery and flow down 4" poly line to DCP meter at HT Fed #8 tank battery. Gas allocation will be based on check meter at #5 tank battery and well tests. E-line will be on-lease down existing roads to connect to power at the existing HT Fed #5 battery.
- 4. Location of Existing Wells in a One-Mile Radius Exhibit A
 - A. Water wells None known
 - B. Disposal wells None known
 - C. Drilling wells None known
 - D. Producing wells As shown on Exhibits "A"
 - E. Abandoned wells As shown on Exhibits "A"

5. Location of Proposed Production Facilities:

If on completion this well is a producer, a 4" surface flowline described above will be laid to the existing HT Fed #5 tank battery and oil, gas, and water allocated based on periodic wells tests. See production facilities layout diagram. Any changes to the facilities or off-site facilities will be accompanied by a Sundry Notice.

6. Location and Type of Water Supply:

Water will be purchased locally from a commercial source and trucked over the access roads.

7. Source of Construction Material:

If possible, native caliche will be obtained from the excavation of drill site. Topsoil will be pushed back from the drill site and existing caliche will be ripped and compacted. Then topsoil will be stockpiled on location as depicted on Exhibit "D" (rig layout). If additional material is needed, it will be purchased from a BLM-approved pit as near as possible to the well



.

.