

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 9:55 am, Jun 27, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OCCIDENTAL PERMIAN LTD.	Contact	TONY AGUILAR
Address	1017 W. Stanolind Road, Hobbs	Telephone No.	575-397-8251
Facility Name	NORTH HOBBS UNIT 24-341	Facility Type	OIL AND GAS PRODUCTION FACILITY

Surface Owner	Occidental Permian LTD.	Mineral Owner	HOBBS (G-SA)	API No.	30-025-05490
---------------	-------------------------	---------------	--------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	24	18-S	37-E					Lea

Latitude_N32.72642_ Longitude_W103.20332_

NATURE OF RELEASE

Type of Release	NA	Volume of Release	0	Volume Recovered	0
Source of Release	NA	Date and Hour of Occurrence	6-17-16 @ 12PM	Date and Hour of Discovery	6-17-16 @ 12PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MAXEY BROWN		
By Whom?	TONY AGUILAR	Date and Hour	6-17-16 @ 12:17PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Cause: POWER POLE CAUGHT ON FIRE, THERE WAS NO GRASS FIRE. ELECTRICIANS ARE STILL INVESTIGATING WHAT CAUSED THE FIRE. POSSIBLE ARC WHEN WIRES TOUCHED.

Remedial Action Taken:
HOBBS FIRE DEPT. AND DEPUTY WAS CALLED OUT AND WAS ABLE TO EXTINGUISH FIRE. AFTER FIRE WAS PUT OUT HFD/DEPUTY LEFT LOCATION. ON 6-21-16 POWER POLES WILL BE CHANGED OUT AND TRANSFORMERS ARE BEING INSPECTED FOR DAMAGE. WILL REWIRE POLE AND OTHER DAMAGED PARTS, AFTER REPAIRS, POWER WILL BE RESTORED.

Describe Area Affected and Cleanup Action Taken.*
NA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: TONY AGUILAR		Approved by Environmental Specialist: 	
Title: HES SPECIALIST		Approval Date: 06/27/2016	Expiration Date: ///
E-mail Address: RAYMOND_AGUILAR@OXY.COM		Conditions of Approval:	
Date: 6-20-16	Phone: 575-397-8251	Attached <input type="checkbox"/> nJXK1617934304	