

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Cimorex Energy	Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059	
Facility Name Bondurant Fed 12H	Facility Type production	
Surface Owner BLM	Mineral Owner	API No. 30-025-40182

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	01	19S	32E	330	N	1916	E	Lea

Latitude 32.6956558 Longitude -103.7174301

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 100 bbls	Volume Recovered 100 bbls
Source of Release Inlet separator	Date and Hour of Occurrence 8/6/2017	Date and Hour of Discovery 8/6/2017
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu/Shelly Tucker	
By Whom? Gloria Garza	Date and Hour 8/6/2017 5:16 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 9:07 am, Aug 31, 2017

Describe Cause of Problem and Remedial Action Taken.*

A leak developed due to corrosion at the bottom of an inlet separator. All fluids were recovered from a falcon lined containment.

Describe Area Affected and Cleanup Action Taken.*

All fluids were contained within a falcon lined containment which was checked for breaches and found to be fully intact.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Supervisor	Approval Date: 8/31/2017	Expiration Date:
E-mail Address: calderman@cimorex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/29/2017 Phone: 432-853-7059	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1724332913

From: [Yu, Olivia, EMNRD](#)
To: ["Christine Alderman"](#); [Shelly Tucker \(stucker@blm.gov\)](mailto:stucker@blm.gov)
Cc: [Gloria Garza](#)
Subject: RE: [External] RE: Cimarex Reportable Spill - Bondurant Fed Com 2
Date: Thursday, August 31, 2017 9:15:00 AM
Attachments: Cimarex_initialC141_20170829141710584.pdf

Good morning Ms. Alderman:

Please see attachment for your records.

Please inspect the liner in question. It is NMOCD's understanding that all impacted material in the containment has been removed and the liner inspected for integrity. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids. Pictures and a record of the removal of contaminated fill or proper disposal of liquids are strongly encouraged to accompany submission of initial C-141s.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

-----Original Message-----

From: Christine Alderman [<mailto:calderman@cimarex.com>]
Sent: Tuesday, August 29, 2017 1:21 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Shelly Tucker (stucker@blm.gov) <stucker@blm.gov>
Cc: agroves@slo.state.nm.us; Gloria Garza <ggarza@cimarex.com>
Subject: RE: [External] RE: Cimarex Reportable Spill - Bondurant Fed Com 2

Ms Yu,

Sorry for the delay in getting this to you.

Christine Alderman

Cimarex Energy Co.

ESH Supervisor - Permian Basin
Midland TX
Cell - 432.853.7059

-----Original Message-----

From: Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]
Sent: Monday, August 28, 2017 10:16 AM
To: Gloria Garza <ggarza@cimarex.com>; Shelly Tucker (stucker@blm.gov) <stucker@blm.gov>
Cc: Christine Alderman <calderman@cimarex.com>; agroves@slo.state.nm.us

Subject: [External] RE: Cimarex Reportable Spill - Bondurant Fed Com 2

Good morning Ms. Garza:

The initial C-141 for this release was due on August 20, 2017. Please be advised that the Responsible Operator currently is not in compliance with NMAC 19.15.29. Also, please note that surface and mineral ownerships are Federal.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

-----Original Message-----

From: Gloria Garza [<mailto:ggarza@cimarex.com>]

Sent: Sunday, August 6, 2017 5:16 PM

To: Houston, Kristen, EMNRD <Kristen.Houston@state.nm.us>; agroves@slo.state.nm.us; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>

Cc: Christine Alderman <calderman@cimarex.com>

Subject: Cimarex Reportable Spill - Bondurant Fed Com 2

All

We had a spill occur today around 4 pm.

The cause appears to be corrosion at the bottom of separator.

100 bbls of produce water was released into a falcon lined containment and 1 barrel of crude oil. Once the vacuum trucks get to location 100% will be recovered.