<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Form C-141

Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Attached

Initial only

Release Notification and Corrective Action

		OPERATOR												
		COG Operati		Contact:			Robert McNeill							
Address:	600 Wes	Telephone No. 432-683-7443												
Facility Nan	ne: Monet	Federal Con	n #003H	Tank Battery		Facility Typ	e: Tank Bar	ttery						
Surface Own	ner:	wner:	Federal			API No. 30-025-42763								
LOCATION OF RELEASE														
Unit Letter	t Letter Section Township Range Feet from the North C 04 25S 33E 190					/South Line North	Feet from the 1980	East/West Line West			ty			
C 04 25S 33E 190 North 1980 West Lea Latitude 32.16674599 Longitude -103.5793769														
NATURE OF RELEASE														
Type of Relea	ase:			1,122,		Volume of Release: Volume Recovered:								
Oil (Fire)							EST. 188 bbls Oil				0 bbls			
Source of Release:											Hour of Discovery:			
Flare Was Immediate Notice Given?							December 6, 2017 8:00 am December 6, 2017 8:00 am If YES, To Whom?							
Yes ☐ No ☐ Not Required														
By Whom? Becky Haskell							Date and Hour: December 6, 2017 1:23 PM							
Was a Watercourse Reached? ☐ Yes ☒ No							If YES, Volume Impacting the Watercourse.							
If a Watercou	rse was Im	pacted, Descri	be Fully.*	:		DE	CENTED							
RECEIVED														
Describe Cause of Problem and Remedial Action Taken * By Olivia Yu at 10:25 am, Dec 18, 2017														
Describe Cause of Problem and Remedial Action Taken.*														
The release/fire was caused by paraffin plugging the supply gas little joe regulator which caused the vessels to lose supply pressure to the dumps, sending														
fluid to the flare. The little joe regulator will be replaced and the lines cleared of paraffin.														
Describe Area	a Affected	and Cleanup A	Action Tak	en.*										
The release/f	ire was cor	stained in the f	irowall ar	ound the flare and	all flui	de burned C	oncho will have th	he cnill	area evaluat	ed for any	nossihl	e impact		
				on work plan to the							possion	c impact		
				is true and comple										
				d/or file certain rel e of a C-141 repor										
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
		ws and/or regu												
and the same of th							OIL CONSERVATION DIVISION							
Signature:		9//												
Printed Name: Dakota Neel						Approved by Environmental Specialist:								
Title:		HSE Coo	dinator			Approval Date: 12/18/2017 Expiration Date:								
E-mail Addre	ess:	dneel2@c	concho.co	<u></u>		Conditions of	onditions of Approval:							

* Attach Additional Sheets If Necessary

575-748-2010

Date: December 14, 2017

nOY1735238080

From: Yu, Olivia, EMNRD

To: "Dakota Neel"; stucker@blm.gov; Billings, Bradford, EMNRD

Cc: James Amos@blm.gov; Sheldon Hitchcock; Christopher Gray; Rebecca Haskell

Subject: RE: (C-141 Initial) Monet Federal Com #003H Battery 12/6/17 (30-025-42763)

Date: Monday, December 18, 2017 10:42:00 AM

Attachments: image002.png

reviewed_(C-141 Initial) Monet Federal Com #003H Tank Battery (Fire) 12-6-2017 (30-25-42763).pdf

Dear Mr. Neel:

The submitted C-141 form is accepted as initial only. Please clarify. Did all 188 bbls. of oil pass directly from the regulator to the flare? Was the area around the flare lined? NMOCD requires verification that there was no impact to the pasture. Please provide photo documentation.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Dakota Neel [mailto:DNeel2@concho.com] Sent: Thursday, December 14, 2017 10:30 AM

To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; stucker@blm.gov; Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>

Cc: James_Amos@blm.gov; Sheldon Hitchcock <SLHitchcock@concho.com>; Christopher Gray <CGray@concho.com>; Rebecca Haskell <RHaskell@concho.com>

Subject: (C-141 Initial) Monet Federal Com #003H Battery 12/6/17 (30-025-42763)

Ms. Yu/Ms. Tucker

Please find the attached Initial C-141 for your consideration. If you have any questions or concerns please contact me.

Thank you,

Dakota Neel HSE Coordinator COG Operating LLC Cell: 432-215-2783 dneel2@concho.com

2407 Pecos Ave. Artesia, NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rebecca Haskell

Sent: Wednesday, December 06, 2017 1:23 PM

To: Olivia Yu (<u>olivia.yu@state.nm.us</u>); <u>stucker@blm.gov</u>

Cc: <u>James Amos@blm.gov</u>; Dakota Neel; Sheldon Hitchcock; Christopher Gray

Subject: (Notification - Release/Fire) Monet Federal Com #003H Battery 12/6/17 (30-025-42763)

Ms. Yu/Ms. Tucker,

COG Operating LLC is reporting a release/fire at the Monet Federal Com #003H Battery Unit C Section 04, Township 25S, Range 33E, GPS 32.16674599, -103.5793769 The release occurred on December 6, 2017.

Released: Approximately 188 barrels.

Recovered: 0 barrels, all fluids were burned in the fire.

The release/fire was caused by paraffin plugging the supply gas little joe regulator which caused the vessels to lose supply pressure to the dumps, sending fluid to the flare. The release/fire was contained in the firewall around the flare and all fluids burned. This area is being evaluated and a C-141 will be submitted. If you have any additional questions please don't hesitate to contact me.

Thank You,

Becky Haskell Senior HSE Coordinator COG Operating LLC 600 W Illinois Avenue | Midland, TX 79701 Direct: 432-818-2372 | Main: 432.683.7443

Cell: 432-556-5130

rhaskell@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.