Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505														
<b>Release Notification and Corrective Action</b>														
						OPERATOR				Initia	al Report	$\boxtimes$	Final Report	
	Name of Company OGRID Number						Contact				<b>`</b>			
EOG Y Resources, Inc. 25575						Robert Asher								
Address 104 S. 4 <sup>th</sup> Street						Telephone No.								
						575-748-1471								
Facility Name Caravan & Convoy State Battery						Facility Type								
Calavalla		Battery												
Surface Owner Mineral Owner						r:				API No. 30-025-41642				
State State										30-025-41642				
LOCATION OF RELEASE														
Unit Letter	Section	Township		h/South Line Feet from the East/West Line County										
В	Feet from the						Lea							
Latitude 32.18149 ongitude -103.57813														
NATURE OF RELEASE														
Type of Rele		Volume of Release			1	Volume Recovered								
Produced Water						35 B/PW				34 B/PW				
Source of Release Valve Plug						Date and Hour of Occurrence 2/13/2017; 8:00 AM			10.02	Date and Hour of Discovery				
Was Immedi		If YES, To Whom?				2/13/2017; 8:00 AM								
Yes No Not Require										REVISED				
By Whom?		Date and Hour												
Robert Ashe		2/15/2017; AM (Email)				4:07 pm, Mar 14, 2018								
Was a Water		If YES, Volume Impacting the Watercourse.												
			REC	CEIN	<b>IED</b>									
If a Watercourse was Impacted, Describe Fully.*						By Olivia Yu at 3:16 pm, Mar 03, 2017								
	Describe Cause of Problem and Remedial Action Taken.*													
Cause of the	Cause of the release was from a psi valve plug on a knockout that broke. Vacuum truck(s) and roustabout crew called.													
Describe Are					. 14	11								
An approximate area of 80'X 20'. The release occurred within a lined/bermed battery where the liner has not been compromised and is integrally sound. Vacuum trucks were called and recovered 34 bbls of the 35 bbls of released produced water. The remaining one (1) bbl of produced water is entrained														
within the gravel and will be removed when the gravel is removed. The removed gravel will be disposed at an NMOCD approved facility. The valve was														
repaired. Depth to Ground Water: >100' (approximately 100', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to														
Surface Water Body: >1000', SITE RANKING IS 0. Based on 97% of the produced water was recovered and the remaining produced water														
entrained in excavated gravel and hauled off for disposal, EOG Y Resources, Inc. requests closure. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and														
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger														
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health														
federal state	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
OIL CONSERVATION DIVISION														
Signature:														
Printed Name: Robert Asher						Approved by Environmental Speciali			pecialist:	iist:				
								0047				~		
Title: Enviro	onmental Sup	pervisor	(K)			Approval Da	te: 3/3/2	2017	E	Expiration	Date:	alamati kana ana ana ana ina ana ina		
E-mail Address: Robert_Asher@eogresources.com						Please insp	ect liner	in que	estion.	Provide	(a) ~~	5. <b>102</b> 27-111		
						Please inspect liner in question. Provide NMOCD with a concise report of the Attached								
Date: March 1, 2017 Phone: 575-748-4217						inspection with affirmation the liner has								
* Attach Additional Sheets If Necessary						and will co								
					nOY180735						7357386			