
Office State of New Mexi	
District I Energy, Minerals and Natural 1625 N French Dr., Hobbs, NM 88240BBS OCD	WELL API NO.
OIL CONSERVATION D	IVISION 30-025-24679
District IV Service 18 2011 1220 South St. Franci	S Dr. 5. Indicate Type of Lease STATE FEE
District IV	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	,
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SPROPOSALS)	
I. Type of Well: Oil Well	8. Well Number
2. Name of Operator	9. OGRID Number
Chevron USA Inc.	4323
3. Address of Operator #15 Smith Rd., Midland, TX 79705	10. Pool name or Wildcat
4. Well Location	Vacuum Abo, North
	1000
Unit Letter F: 1980 feet from the North	line and 1980 feet from the West line
Section 15 Township 17-S Rang	e 34-E NMPM Lea County
11. Elevation (Show whether DR, R.	KB, RT, GR, etc.)
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-	144 must be attached)
Pit Location: UL F Sect 15 Twp 17-S Rng 34-E Pit type Steel Dept	
Distance from nearest surface water Below-grade Tank Location UL	
1980 feet from the North line and 1980 feet from the West line (Stee	el Tank <u>)</u>
12. Check Appropriate Box to Indicate Natu NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☑ FROM 1.	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C	SUBSEQUENT REPORT OF: REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ TEMPORARILY ABANDON □ CHANGE PLANS □ PULL OR ALTER CASING □ MULTIPLE □ CONTROL OF ALTER CASING □ MULTIPLE □ CONT	SUBSEQUENT REPORT OF: REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION	SUBSEQUENT REPORT OF: REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMPLETION COM	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT RASING TEST AND ABANDONMENT REMENT JOB OTHER. Linent details, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all performs of starting any proposed work). SEE RULE 1103. For Multiple Cor recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (shi	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING CASING ABANDONMENT RASING TEST AND ABANDONMENT REMENT JOB OTHER. Unionent details, and give pertinent dates, including estimated date Completions: Attach wellbore diagram of proposed completion DOE/B.Salt est./liner top) WOC&TAG.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all perform of starting any proposed work). SEE RULE 1103. For Multiple Cor recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (show 7. Perf and squeeze 70sx cement plug from 1655'-1455' (T.S.)	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING ALTERING CASING ALTERING AL
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all perform starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (show 7. Perf and squeeze 70sx cement plug from 1655'-1455' (T.S. 8. Perf and squeeze 140sx cement plug from 400'-surface' (show 150 to 15	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING ALTERING CASING ALTERING AL
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all perform of starting any proposed work). SEE RULE 1103. For Multiple Cor recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (show 7. Perf and squeeze 70sx cement plug from 1655'-1455' (T.S.)	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING ALTERING CASING ALTERING AL
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all perform of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (show 7. Perf and squeeze 70sx cement plug from 1655'-1455' (T.S. 8. Perf and squeeze 140sx cement plug from 400'-surface' (9. Install dryhole marker and clean location.	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all perform starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (show 7. Perf and squeeze 70sx cement plug from 1655'-1455' (T.S. 8. Perf and squeeze 140sx cement plug from 400'-surface' (show 150 to 15	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMPLETION C	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING ALTERING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: 13. Describe proposed or completed operations. (Clearly state all perform of starting any proposed work). SEE RULE 1103. For Multiple or recompletion. 6. Perf and squeeze 75sx cement plug from 3230'-2663' (sh. 7. Perf and squeeze 70sx cement plug from 1655'-1455' (T.S. 8. Perf and squeeze 140sx cement plug from 400'-surface' (9. Install dryhole marker and clean location. I hereby certify that the information above is true and complete to the best grade tank has been/will be constructed or closed according to NMOCD guidelines , a	SUBSEQUENT REPORT OF: REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PULL OR ALTER CASING MULTIPLE COMPLETION COMPLET	SUBSEQUENT REPORT OF: REMEDIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMPLETION C	SUBSEQUENT REPORT OF: REMEDIAL WORK

. .

1-150 L 04/05 900 005



CURRENT WELLBORE DIAGRAM

NVAWU #2 WELL ID INFORMATION Lease Name North Vacuum Abo West Unit Vacuum North New Mexico Lea Reservoir Abo 1980 FNL & 1980 FWL Sec 15, T-17S, R-34E Ref# 30-025-24679 API# DF GL 4051 Original Spud Date 11 3/4" Original Compl Date 9/3/1974 42# 300' 250 sx, circulated Surface 15" 8 5/8" 28# 3130' 400sx 10/18/1984 Tubing Detail Date: calc 75% 11" # Jts. Footage Size_ 2-3/8" IPC tubing 5 1/2" 17# 2763' - 8976' 1050sx 3100' 7 7/8" Abandoned SA perfs 4716' - 4726' Abandoned Glorieta Perfs 6241' - 6452'

UPDATED BY Cassie Viets
DATE 4/27/2004

Abo Perforations: 8761' - 8912'

5-1/2" Lock-Set Packer Set @ 8658'

PBTD: 8988