Form 3160-5 (June 2015)

UNITED STATES

Rec'd 06/16/2020 - NMOCD

FORM APPROVED OMB NO. 1004-0137

DEPARTMENT OF THE INTERIOR Expires: January 31, 2018 BUREAU OF LAND MANAGEMENT 5. Lease Serial No. NMNM99041 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for such proposals.					o. If Indian, Anouee of Tribe Name		
SUBMIT IN T	7. If Unit or CA/Agreement, Name and/or No.						
Type of Well	8. Well Name and No. SPRUCE GOOSE FEDERAL 1						
Name of Operator COG OPERATING LLC	9. API Well No. 30-025-38445						
3a. Address 600 W. ILLINOIS AVE MIDLAND, TX 79701 3b. Phone No. Ph: 432-580			clude area code))	10. Field and Pool or Exploratory Area LUSK; BONE SPRING, NORTH		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, S	State	
Sec 8 T19S R32E 19S 32E 32.681358 N Lat, 103.798420 W Lon					LEA COUNTY COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Deepen		☐ Produc	tion (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing		lic Fracturing	☐ Reclam	nation	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair		onstruction R	Recom	PRIFCT TO	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans		d Abandon	A Temp	TATILY ABANDENITO	AND	
	☐ Convert to Injection	☐ Plug Ba	C 1 - C 1	A Water	OLS ATTACAMENT		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting at a plant to the post of the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with PMPL Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. POH w/ rods and tubing. 2. RIH and tag existing 5 1/2" CIBP @ 8,425'. 3. Set 5 1/2" CIBP @ 8224'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 8224-8074'. 4. Spot 25 sx cmt @ 5900-4800' (Bone Spring) £6137' - £767') 5. Spot 25 sx cmt @ 5900-4800' (Bone Spring) £6137' - £767') 5. Spot 25 sx cmt @ 1384-3184'. WOC & Tag (13 3/8" Shoe) 6. Perf & Sqz 50'sx cmt @ 1024-824'. WOC & Tag (13 3/8" Shoe) 6. Perf & Sqz 50'sx cmt @ 1024-824'. WOC & Tag (13 3/8" Shoe) 7. Perf & Sqz 70'sx cmt @ 307'-Surface. (T/Salt) 9. Cut off wellhead, verify cmt to surface, weld on Below Ground Dry Hole Marker.							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #510201 verified by the BLM Well Information System							
For COG OPERATING LLC, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 04/09/2020 ()							
Name (Printed/Typed) ABIGAIL	ANDERSON			ATORY			
Signature (Electronic	Submission)	D	ate 04/08/2	2020			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
_Approved_ByLongVo Conditions of approval, if any, are attached	Z. Approval of this notice does		Title Pet	oleum	Engineer	Date 4/2 6/26	

A

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

CFC Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Prospect Lusk Spruce Goose Federal #1 Reservoir: Bone Spring Location: Current Well ID Info: Footage: 330' FNL, 430' FEL, Unit A Wellbore Diagram API No: 30-025-38445 Section: Spud Date: 8/2/2007 195 Township Range 32E Hole Size: 17-1/2" County: Lea, NM 13-3/8" 54.5# J-55 974 Surf. Csg: Set @ Cement w/ Long: 800 sx Elevations: 1 Circ: 3,639 yes TOC: surface KB: KB Calc ck w/log? Date History 8/2/2007 Spud Well 9/13/2007 Perf Bone Spring from 8,541' - 8,550' & 8,451' - 8,460' 10/11/2007 Set CIBP @ 8,425' and recomplete Bone Spring 8,274' - 8,284' 10/23/2007 Run pump and rods 4/8/2009 NPA. L/D pump and RBIH w/ new 11/8/2016 RTP after offset frac prep TUBING DETAIL 11/07/2016 254 JOINTS OF 2-7/8 TUBING (8068.98) Hole Size: 12-1/4" 2FT MRK SUB Surf. Csg: 9-5/8" 36# J-55 TAC (8137.14) SET WITH 20 POINTS Set @ 3,438 Cement w/ 1.100 sx 6-JOINTS OF 2-7/8 TUBING Circ: TOC: yes surface MSN/NO DIP TUBE (8329.98) 16FT MULE SHOE JOINT (EOT 8346.00) ROD DETAIL 11/08/2016 2.5x1.25xRHBMx20x6x4x(B-2608) 6-1.500 SINKER BARS 150-3/4 STEEL RODS 89-7/8 STEEL RODS 87-1.00 STEEL RODS 1-4FT SUB Perf Bone Spring Sand 8,274' - 8,284', 33 shots EOT @ 8,346 CIBP set @ 8,425'. NEW PBTD Perf Bone Spring Sand 8,451' - 8,460', 10 shots Perf Bone Spring Sand 8,541' - 8,550', 10 shots Hole Size: 7-7/8 PBTD 9,440' Prod. Csg: 5-1/2" 17# N-80 LTC TD 10,673 Set @: 9,508 Cement 1st Stg w/: Lead 135 sx HLP, tailed w/ 375 sx PB super H

Cement 2nd Stg w/: Lead 500 sx HLP, tailed w/ 200 sx PB super H 1st stage: 100sx, 2nd stage: none

TOC:

Prospect:	Lusk	Spruce Goose Fede	eral #1
	Location:		Reservoir: Bone Spring
Footage:	330' FNL, 430' FEL, Unit A	Current	Well ID Info:
Section:	7	Wellbore Diagram	Soud Date: Support
Township	198		8. Perf & Sqz 70 sx cmt @ 307'-Surface. (T/Sait) Ve if & Quelay
Range County:	32E Lea, NM		
Lat:			Hole Size: 17-1/2" Surf. Csg: 13-3/8" 54.5# J-55
Long:	Elevations:		Set @ 974
GL:	3,639'		Cement w/ 800 sx Circ: ves
KB: KB Calc:			Circ: yes TOC: surface
ck w/log?			60 t×
			7. Perf & Sqz 56 sx cmt @ 1024-824', WOC & Tag (13
Date	History		3/8" Shoe)
			10 cr 1085
	Spud Well Perf Bone Spring from 8,541' - 8,550' & 8,451' - 8,460'		6. Perf & Sqz 50 sx cmt @ 1384- 1464'. WOC & Tag
10/11/2007	Set CIBP @ 8,425' and recomplete Bone Spring 8 274' - 8 284'		(B/Salt) (T. Salt @ 1150')
10/23/2007	Run pump and rods NPA. L/D pump and RBIH w/ new		
			alacial acido a Chan TAL
11/8/2016	RTP after offset frac prep	WICLE	e (2600'-2514') Perf & sqz. TAG
THEN	A PATE 11 11 11 11 11 11 11 11 11 11 11 11 11		45 5×
	G DETAIL 11/07/2016		
254 JC	INTS OF 2-7/8 TUBING (808	88.98)	(Yates @ 2590')
2FT M	RK SUB		/
TACIA	3137.14) SET WITH 20 POIN	те	TOC @ 3000'
6-101	ITS OF 2-7/8 TUBING	13 1	5. Spot 25 sx cmt @ 3488-3288'. WOC & Tag (9 5/8"
RECEIN	O DID TUDE (DOING		Shoe Hole Size: 12-1/4"
MONIN	O DIP TUBE (8329.98)		Surf. Csg: 9-5/8" 36# J-55
16FT N	MULE SHOE JOINT (EOT 834	46.00)	Set @ 3,438' Cement w/ 1,100 sx
	*		Circ: yes
			TOC: surface
ROD	DETAIL 11/08/2016		
Z. DX 1.	25xRHBMx20x6x4x(B-2	608)	-(4918' - 4768') spot 25 88
6 - 1.50	0 SINKER BARS	10000	Pelaware @ 4868'
	4 STEEL RODS		veraware & 4868'
	The same of the sa		
89-7/8	STEEL RODS		4. Spot 25 sx cmt @.5000-4800' (Bone Spring) @ 6827'
87-10	0 STEEL RODS		
			(6937'-6767')
1-4F.T	208		
			,
		5/25/ 74/3/25/ Sept.	3. Set 5 1/2" CIBP @ 8224'. Circulate hole w/ MLF.
			Pressure test csg. Spot 25 sx cmt @ 8224-8074'.
			Perf Bone Spring Sand 8,274' - 8,284', 33 shots
			2. RIH and tag existing 5 1/2" CIBP @ 8,425'.
			1. POH w/ rods and tubing. CIBP set @ 8,425'. NEW PBTD
			Perf Bone Spring Sand 8,451' - 8,460', 10 shots
			Perf Bone Spring Sand 8,541' - 8,550', 10 shots
			Hala Cinn.
		PBTD 9,440'	Hole Size: 7-7/8" Prod. Csg: 5-1/2" 17# N-80 LTC
		TD 10,673'	Set @: 9,508'
			Cement 1st Stg w/: Lead 135 sx HLP, tailed w/ 375 sx PB super H
C:\Users\RCM\Des	kton/Well Files to Build/COG Basin Pound 33 DICOGGO		

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the $90^{\rm th}$ day provide this office, prior to the $90^{\rm th}$ day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. Blowout Preventers: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken: From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlshad, New Mexico 88220-6292 mn/vog.mid.www



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, serap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide crosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
- For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the
- Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify

- The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists: Jim Amos

Supervisory Petroleum Engineering Tech 575-234-3909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

Revisions to Operator-Submitted EC Data for Sundry Notice #510201

Operator Submitted

ABD NOI

NMNM99041 Lease:

Agreement:

Sundry Type:

Operator:

COG OPERATING LLC 600 W. ILLINOIS AVE MIDLAND, TX 79701 Ph: 432-683-7443

Admin Contact:

ABIGAIL ANDERSON

REGULATORY

E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

Tech Contact:

ABIGAIL ANDERSON REGULATORY

E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

Location:

State:

NM

County: LEA COUNTY

Field/Pool:

LUSK; BONE SPRING, NORTH

Well/Facility:

SPRUCE GOOSE FEDERAL 1

Sec 8 T19S R32E 19S 32E

32.681358 N Lat, 103.798420 W Lon

BLM Revised (AFMSS)

ABD

NOI

NMNM99041

COG OPERATING LLC ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701-4287 Ph: 432.685.4342

ABIGAIL ANDERSON

AGENT

E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

ABIGAIL ANDERSON

AGENT

E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

NM

LEA

N LUSK

SPRUCE GOOSE FEDERAL 01 Sec 7 T19S R32E NENE 330FNL 430FEL