Rec'd 7/20/2020 - NMOCD

Office	State of New Mexico	Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-46338
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sulta 1 0, 1111 0, 505	o. State on & Gas Lease No.
87505		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH	SAVAGE 2 STATE COM
PROPOSALS.)	EICATION FOR FERWIT (FORM C-101) FOR SOCI	0 777 11 27 1
1. Type of Well: Oil Well	Gas Well Other	8. Well Number 721H
2. Name of Operator EOG	RESOURCES INC	9. OGRID Number 7377
3. Address of Operator		10. Pool name or Wildcat
PO BC	OX 2267 MIDLAND, TX 79702	WC025 G09 S253309P;UPR WOLFCAMP
4. Well Location		
Unit Letter C	: 527' feet from the NORTH line and	1695' feet from the WEST line
Section 2	Township 25S Range 32E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR, e	
3520' GR		
12. Check	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
		•
		JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING		ENT JOB
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM		
		ampletien M
OTHER:	OTHER: C	ompletion and give pertinent dates, including estimated date.
OTHER: 13. Describe proposed or com	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple	and give pertinent dates, including estimated date
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to frace	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. - Test void to 5000 psi, seals & flanges to 850	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. - Test void to 5000 psi, seals & flanges to 850 rac	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. Test void to 5000 psi, seals & flanges to 850 ac perf & frac, 12,635 -17,454', 1077 3 1/8" shots	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. D- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. D- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a 07/01/2020 Opened well to flo	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore owback - Date of First Production	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a 07/01/2020 Opened well to flo	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a 07/01/2020 Opened well to flo	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore owback - Date of First Production	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a 07/01/2020 Opened well to flo	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore owback - Date of First Production	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or result of the control	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore owback - Date of First Production 3-6 months once flowback is complete	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 1, 12,218,682lbs proppant +
OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re 11/01/2019 Rig released 11/18/2019 MIRU prep to fract 02/28/2020 Begin perf and Fract 03/07/2020 Finish 17 stages p 250,118 bbls load 03/11/2020 Drilled out plugs a 07/01/2020 Opened well to flo	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots a fluid and clean out wellbore pwback - Date of First Production 3-6 months once flowback is complete	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or result of the control	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore owback - Date of First Production 3-6 months once flowback is complete	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 1, 12,218,682lbs proppant +
OTHER: 13. Describe proposed or com of starting any proposed we proposed completion or result of the proposed completion	repleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots a fluid and clean out wellbore powback - Date of First Production 3-6 months once flowback is complete Rig Release Date: 11/	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 5, 12,218,682lbs proppant +
OTHER: 13. Describe proposed or com of starting any proposed we proposed completion or result of the proposed completion	ppleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots of fluid and clean out wellbore owback - Date of First Production 3-6 months once flowback is complete	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 5, 12,218,682lbs proppant +
OTHER: 13. Describe proposed or comof starting any proposed was proposed completion or result of the proposed completion	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots a fluid and clean out wellbore powback - Date of First Production 3-6 months once flowback is complete Rig Release Date: 11/	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 6, 12,218,682lbs proppant +
OTHER: 13. Describe proposed or comof starting any proposed was proposed completion or result of the proposed completion	repleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. C- Test void to 5000 psi, seals & flanges to 850 rac perf & frac, 12,635 -17,454', 1077 3 1/8" shots a fluid and clean out wellbore powback - Date of First Production 3-6 months once flowback is complete Rig Release Date: 11/	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 6, 12,218,682lbs proppant + 01/2019
OTHER: 13. Describe proposed or comof starting any proposed was proposed completion or research to the proposed completion or research	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. Description: Descriptio	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 6, 12,218,682lbs proppant + 01/2019 edge and belief. DATE 7/20/2020
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or result of the proposed completio	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. Description: Descriptio	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 6, 12,218,682lbs proppant +
OTHER: 13. Describe proposed or comof starting any proposed was proposed completion or research to the proposed completion or research	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. Description: Descriptio	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 6, 12,218,682lbs proppant + 01/2019 edge and belief. t
OTHER: 13. Describe proposed or come of starting any proposed was proposed completion or result of the proposed completio	npleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple ecompletion. Description: Descriptio	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 0 psi 6, 12,218,682lbs proppant + 01/2019 edge and belief. DATE 7/20/2020