Submit I Copy To Appropriate District Office	State of Ne				Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources			WELL API NO.		
District II ~ (575) 748-128.3	1625 N. French Dr., Hohbs, NM 88240 District II ~ (575) 748-1283				30-025-37161	
811 S First St., Artesia, NM 88210				5. Indicate Type of Le	ease	
<u>District III</u> - (505) 334-6178 1000 Rio Bruzos Rd, Aztec, NM 87410	1220 South St. Francis Dr.			STATE FEE 🖂		
District IV - (505) 476-3460	Santa Fe, NM 87505			6. State Oil & Gas Le	Toronto.	
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Uni	t Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.)				W H TURNER 8. Well Number 3		
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator						
GRIZZLY OPER ATING, LLC				9. OGRID Number 258350		
3. Address of Operator				10. Pool name or Wildcat		
5847 SAN FELIPE, STE. 3000, HOUSTON, TEXAS, 77057			TUBB; BLINEBRY; PADDOCK			
4. Well Location						
Unit Letter_K:_2,310feet from the _SOUTH line and2,270 feet from theWESTline						
Section 29 Township 21S Range 37E NMPM County LEA						
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
3,483 GR						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				_	TERING CASING	
TEMPORARILY ABANDON				·· =	AND A	
PULL OR ALTER CASING				_		
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM		_ 1				
OTHER: Temporarily Abandon (TA) 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dates.)						
of starting any proposed w	pleted operations. (Clearly s	state all pe	ertinent details, an	d give pertinent dates, i	hore diagram of	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
Grizzly Operating, LLC has temporarily abandoned (TA) this well as follows:						
1. MIRU WS. LD production equipment.						
2. RU WL. Set CIBP @ 5,000` (top perf @ 5,092`). Cap w/ 35` of cmt via bailer.						
3. Fill casing with treated water and pressure test to 500 psig for at 30 minutes. Pressure chart attached to this sundry.						
4. RD WL & WS.						
			EINIA1 7	TA CTATUS EVE	ENCION	
		Ann		<u> IA STATUS- EXT</u> XPIRES: 10/20/2		
						
Spud Date: Well needs to be PLUGGED OR RETURNED to PRODUCTION						
BY THE DATE STATED ABOVE: _ X +						
		71			- / /	
I hereby certify that the information	above is true and complete	e to the be	est of my knowled	ge and belief.		
9J.4 D.7:						
SIGNATURE YEAR D ZIMI	TITL	E_Ope	erations Engineer_	DATE_	10/26/2020	
Type or print name Kyle Zimmermann E-mail address: kzimmerman@grizzlyenergyllc.com PHONE: 432-202-0145						
For State Use Only						
Name 1 1/2						
APPROVED BY: TITLE Compliance Officer A DATE 10/27/20 Conditions of Approval (if any)						
Conditions of Approval (if any						

