

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Received NMOCD 10/14/20

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-025-30334

5. Indicate Type of Lease

STATE X FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

State P

8. Well Number 006

9. OGRID Number

21566

10. Pool name or Wildcat
Wilson; Yates, 7RVS Assoc.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well X Other

2. Name of Operator

Stearns

3. Address of Operator

HC65 Box 988, Crossroads, NM 88114

4. Well Location

Unit Letter B : 100 feet from the North line and 1520 feet from the East line
Section 24 Township 21S Range 34E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒ XX
CASING/CEMENT JOB ☐ PNR

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


9/30/2020 Move in and rig up. Kill well and install BOP. Start out of the hole with tubing.

10/1/2020 Finish pulling tubing. Made gauge ring run and set 7" CIBP on wireline at 3490'. RIH with tubing and tagged CIBP. Circulated MLF and tested casing to 600#. Casing good. Spot 25 sx cement on top of CIBP. POOH to 1705' and SION.

10/2/2020 Spot 35 sx cement at 1705' with CaCl. WOC and tagged cement at 1514'. POOH to 403' and circulated cement to surface inside the 7" casing. Took 70 sx. Lay down remaining tubing and rigged down. Dug out and cut off wellhead. Filled up 7" and 9 5/8" casing strings with 10 sx cement. Installed marker.

12/4/2020 - PM NMOCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Plugging Supervisor DATE 10/4/2020

Type or print name Bobby Stearns E-mail address: bobbystearns1@yahoo.com PHONE: 575-760-2482

For State Use Only

APPROVED BY:  TITLE Compliance Officer A DATE 12/4/20

Conditions of Approval (if any)