Submit 1 Copy To Appropriate District State of New Mexico HOBBS OCD- RECEIVED 11/23/20 Form C-103	
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-46627 5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.	STATE & FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	E-1937
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Poll Take Hode Courts
PROPOSALS.)	8. Well Number 226H
1. Type of Well: Oil Well X Gas Well Other	Z30H
2. Name of Operator Kaiser-Francis Oil Company	9. OGRID Number 12361
3. Address of Operator	10. Pool name or Wildcat
P. O. Box 21468, Tulsa, OK 74121-1468	Bell Lake; Bone Spring, South
4. Well Location	
Unit Letter I : 1920 feet from the South line and	
Section 05 Township 24S Range 34E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM Lea County
3576	
The state of the s	Co.
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON	ILLING OPNS.□ PAND A □
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE	*
CLOSED-LOOP SYSTEM	
	Casing Detail
OTHER: OTHER:	Casing Detail ad give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: OTHER: OTHER: OTHER:	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 set dested to 1500# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 set dested to 1500# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxs	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstated to 1500# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstated to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstated to 1500# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstated to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstated to 1500# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good.	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good.	and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstatested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstatested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good.	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstatested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstatested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stated to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstatested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstatested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 statested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sax tested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sax tested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure are surface. Pressure for a surface pressure for a surfa
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/ I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE And Advanced SIGNATURE TITLEMER., Regulatory Type or print name Charlotte Van Valkenburg E-mail address: Charlotv@k	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure are surface. Pressure for a surface pressure for a surfa
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 stested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/ I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLEMER., Regulatory Type or print name Charlotte Van Valkenburg E-mail address: Charlotv@k For State Use Only	d give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure yr/2020 ge and belief. Compliance DATE 11/23/2020 xfoc.net PHONE: 918-491-4314
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 3/26/2020 13 3/8", 54.5#, J55 set @ 1350' & cmt'd w/1125 stested to 1500# - good. 3/29/2020 9 5/8", 40#, P110 set @ 5132' & cmt'd w/1335 sxstested to 1500# - good. 4/07/2020 5 1/2", 20#, P110 set @ 18770' & cmt'd w/3550 sxstested to 10,000# - good. Spud Date: 3/25/2020 Rig Release Date: 4/ I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE And Advanced SIGNATURE TITLEMER., Regulatory Type or print name Charlotte Van Valkenburg E-mail address: Charlotv@k	ad give pertinent dates, including estimated date ompletions: Attach wellbore diagram of sxs. TOC @ surface. Pressure s. TOC @ surface. Pressure xs. TOC @ surface. Pressure are surface. Pressure for a surface pressure for a surfa