	State of New Mexiconobbs OCD	- RECEIVED 11/20/20 Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30–025–46628
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE K FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		E-1937
	OTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A PLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Bell Lake Unit South
PROPOSALS.)		0 777 1137 7
1. Type of Well: Oil Well 2. Name of Operator	Gas Well Other	8. Well Number 434H 9. OGRID Number
	-Francis Oil Company	12361
3. Address of Operator		10. Pool name or Wildcat
	D. Box 21468, Tulsa, OK 74121-1468	Bell Lake; Wolfcamp, South
4. Well Location Linit Letter I 1950 feet from the South line and 1990 feet from the Fact line		
Unit Letter J : 1950 feet from the South line and 1980 feet from the East line		
Section 05	Township 24S Range 34E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM Lea County
		8 GR
12. Chec	k Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF	INITENTION TO	ACCULENT DEPORT OF
PERFORM REMEDIAL WORK		SEQUENT REPORT OF: CREATER ALTERING CASING CREATER ALTERING CREATER ALTERING CASING CREAT
TEMPORARILY ABANDON		ILLING OPNS. P AND A
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐ CASING/CEMEN	
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	OTHER CO	cinc Dotoil
OTHER:		sing Detail 🗓
13 Descripe proposed or co	impleted oberations of feativ state all berithent details at	d give pertinent dates including estimated date
		nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
	I work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
 of starting any proposed proposed completion or 	work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion.	empletions: Attach wellbore diagram of
of starting any proposed proposed completion or 2/29/2020 13 3/8",	I work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	empletions: Attach wellbore diagram of
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to	work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 950# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4",	work). SEE RULE 19.15.7.14 NMAC. For Multiple Corecompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to	work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 set 1500# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2	<pre>d work). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 5950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 s</pre>	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to	Nowork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 o 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 o 2500# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 s	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2	Nowork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 o 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 o 2500# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good.	empletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good. Rig Release Date: 3	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure 11/20/2020 - PM NMOCD
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good.	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure 11/20/2020 - PM NMOCD
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good. Rig Release Date: 3 Tion above is true and complete to the best of my knowled.	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure and belief.
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good. Rig Release Date: 3	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure and belief.
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	Nework). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good. Rig Release Date: 3 tion above is true and complete to the best of my knowled.	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure 21/20/2020 11/20/2020 - PM NMOCD ge and belief.
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	New ork). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good. Rig Release Date: 3 Tion above is true and complete to the best of my knowled.	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure 21/20/2020 11/20/2020 - PM NMOCD ge and belief.
of starting any proposed proposed completion or 2/29/2020 13 3/8", tested to 3/02/2020 10 3/4", tested to 3/07/2020 7 5/8", 2 tested to 3/21/2020 5 1/2", 2 tested to 5/21/2020 5 1/2", 2	Nework). SEE RULE 19.15.7.14 NMAC. For Multiple Correcompletion. 54.5#, J55 set @ 1315' & cmt'd w/1460 or 950# - good. 45.5, L80 set @ 5124' & cmt'd w/1485 so 1500# - good. 29.7# P110 set @ 10941' & cmt'd w/1615 or 2500# - good. 20#, P110 set @ 19602' & cmt'd w/1445 so 10,000# - good. Rig Release Date: 3 tion above is true and complete to the best of my knowled.	mpletions: Attach wellbore diagram of sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure sxs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure xs. TOC @ surf. Pressure 21/20/2020 11/20/2020 - PM NMOCD ge and belief. Compliance DATE 11/20/2020 kfoc.net PHONE: 918-491-4314