
Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N French Dr., Hobbs, NM 88240		October 13, 2009 WELL API NO.	
			30-025-01871
District II – (575) 748-1283 811 S First St, Artesia, NM 8824 OBBS OCD OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of Lease
			STATE FEE
1000 Rio Brazos Rd , Aztec, NM 87410  District IV = (505) 476-3460  Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
District IV – (505) 476-3460 1220 S'St Francis Dr, Santa Fe <b>Aula 1 5 2011</b> 87505			VO-6340
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR THE DO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR THE DESCRIPTION FOR DEEPEN OR PLUG BACK TO A			East Saunders Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )			8. Well Number
1. Type of Well: Oil Well 🛱 Gas Well 🗹 Other			1 /
2. Name of Operator			9. OGRID Number /
Pride Energy Company			151323
3. Address of Operator			10. Pool name or Wildcat Wildcat
P.O. Box 701950, Tulsa, OK 74170-1950		High Plains; Wolfcamp, N.E.	
4. Well Location			
Unit Letter F: 1,980 feet from the North line and 1,980 feet from the West line			
Section 12 Township 14S Range 34E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4,092 GR			
to of the Park I the New CNI die Breeden Other Date			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTE	ENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR			K ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR			LLING OPNS. ☐ P AND A ☐
PULL OR ALTER CASING   M	MULTIPLE COMPL	CASING/CEMEN	T JOB .
DOWNHOLE COMMINGLE			
OTHER: OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1. Propose to set a CIBP in the 5 ½" casing at 9,800 and dump 35' of cmt. on top of it. (Note: top perf. at 9,868')			
· ·			
2. Pressure up on the 5 $\frac{1}{2}$ " casing to 1,000 # psi, verify it will hold pressure. (OCD to witness).			
3. Temporarily abandon well.			
Condition of Approval : Notify OCD Hobbs			
office 24 hours prior to running MIT Test & Chart			
		r	
Spud Date:	Rig Release Da	ate:	
Spud Bute.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
President of Pride Oil and Gas Co., Inc.,			
SIGNATURE President of Pride Oil and Gas Co., Inc.,  TITLE as General Partner of Pride Energy Company DATE 8/11/11			
/			
Type or print name John W. Pride E-mail address: johnp@pride-energy.com PHONE: 918-524-9200			
For State Use Only			
APPROVED BY: DATE 8-18-2011			
Conditions of Approval (12 any)			
/ (/			4760 -1-

## **BEFORE T & A**



## AFTER T & A

