

Submit 1 Copy To Appropriate District Office
District I -- (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II -- (575) 748-1283
811 S. First St., Artesia, NM 88210
District III -- (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV -- (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received NMOCD 1/25/21
Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-21022
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Barry D. Lee dba Barry Lee Investments		6. State Oil & Gas Lease No.
3. Address of Operator HC65 Box 222, Crossroads, NM 88114		7. Lease Name or Unit Agreement Name Brahman ACC State
4. Well Location Unit Letter <u>B</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>16</u> Township <u>8S</u> Range <u>31E</u> NMPM Chaves County		8. Well Number <u>001</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 273546
		10. Pool name or Wildcat Siete; San Andres

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒ XX
CASING/CEMENT JOB ☐ PNR

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Owner DATE 12/14/2020

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Kerry Fortner TITLE Compliance Officer A DATE 1/25/21

Conditions of Approval (if any)

**Plugging Report
Brahman ACC State #1
30-005-21022**

11/18/2020 Move in rig up and unseat the pump.

11/19/2020 Laid down the rods and installed the BOP. POOH with tubing.

11/20/2020 Set 4 ½" CIBP at 3688'. RIH with tubing and tagged CIBP. Circulated MLF and tested casing to 600#. Casing good. Spot 25 sx Class C cement on top of CIBP. POOH and perforated 4 ½" casing at 1800'. Set packer at 1417' and pressured up on perms to 500#. Held with no pressure drop. Bled off pressure and pressured up to 750#. No drop in pressure. POOH with packer and RIH with tubing and spotted 25 sx cement from 1868'. POOH and SION.

11/23/2020 Tagged cement at 1536'. POOH with tubing and nipped down the wellhead. Removed surface casing flange and installed pull stub. Worked 4 ½" casing off of the slips. Cut casing at 1395' and laid down. RIH with tubing to 1481' and spot 60 sx cement with CaCl. POOH and SION.

11/24/2020 Tagged cement at 1136'. POOH to 257' and circulated cement to surface with 70 sx. Rig down and cut off wellhead. Cement was at surface inside the 8 5/8" casing. Installed marker, removed the anchors and cleaned the steel pit. Move equipment out.