Office Energy, Minerals and Natural Resources	
	May 27, 2004
District II  1625 N. French Dr., Hobbs, NM 8724 OBBS OCD District II  1301 W. Grand Ave, Artesia, NM 88210 District III  1220 South St. Francis Dr.	WELL API NO.
District II OIL CONSERVATION DIVISION	30-025-04552
District III CED 9 2011 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III SEP 23 2011 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE TEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: EUNICE MONUMENT SOUTH UNIT
PROPOSALS.)	
1. Type of Well: Oil Well  Gas Well  Other	8. Well Number
2. Name of Operator	9. OGRID Number
XTO ENERGY, INC. ATIN: PATTY URIAS	005380
3. Address of Operator	10. Pool name or Wildcat
200 N. LORAINE, SUITE 800, MIDLAND, TEXAS 79701	EUNICE MONUMENT; CRAYBURG/SAN ANDRES
4. Well Location	ECHLOS FERMINAL, GRAIDORS, GAR PROJECT
Unit Letter C: 330 feet from the NORTH line and	2310 feet from the WEST line
Offit Letter feet from the fme and _	rect from the new fine
Section 07 Township 21s Range 36E	NMPM County IEA
11. Elevation (Show whether DR, RKB, RT, GF 3,607' - GL	R, etc.)
Pit or Below-grade Tank Application □ or Closure □	Service A Service Andrews Service Service Control and American Service
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well *	Distance from nearest surface water *
Pit Liner Thickness: mil Below-Grade Tank: Volumebbk; Constr	
Fit Liner Trickness: niu Denow-Grade Tauk. Volume	ucton material
12. Check Appropriate Box to Indicate Nature of Notin NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	JBSEQUENT REPORT OF:
	<u> </u>
TEMPORARILY ABANDON	ILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TEST A	ILLING OPNS. PLUG AND ABANDONMENT  ABROVED for plugging of well hore only.
PULL OR ALTER CASING	ILLING OPNS. PLUG AND X ABANDONMENT
PULL OR ALTER CASING	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt f C-103 (Subsequent Report of Well Plugging) hich may be found at OCD Web Page under orms, www.cmurd.scate.mm.us/ocd.
PULL OR ALTER CASING	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt f C-103 (Subsequent Report of Well Plugging) hich may be found at OCD Web Page under orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE CASING TEST ACCEMENT JOB LOOK OTHER:  OT	PLUG AND ABANDONMENT  APROved for plugging of well bore only.  iability under bond is retained pending receipt f C-103 (Subsequent Report of Well Plugging) hich may be found at OCD Web Page under orms, www.cmmrd.scare.mm.us/ocd.  give pertinent dates, including estimated date ach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE CASING TEST ACCEMENT JOB LOOK OTHER:  OTHER: OTHER: WITH JOB LOOK OTHER: WITH JOB LOOK OF Starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion.  O9/16/11: RIH W/ TBG. X TAG PBTD @ 3,662'; ATTEMPT TO WASH DOWN HOUNSUCCESSFUL; PUMP A 40 SX. OMT. PLUG @ 3,662'; WCC.	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date  ach wellbore diagram of proposed completion  LE W/ FRESH WATER (PER NMOCD) BUT WAS
PULL OR ALTER CASING MULTIPLE CASING TEST ACCEMENT JOB LOOK OTHER:  OT	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date  ach wellbore diagram of proposed completion  LE W/ FRESH WATER (PER NMOCD) BUT WAS
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST ACCEMENT JOB L.  OTHER: OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion.  09/16/11: RIH W/ TBG. X TAG PBTD @ 3,662'; ATTEMPT TO WASH DOWN HOUSUCCESSFUL; PUMP A 40 SX. CMT. PLUG @ 3,662'; WCC.  09/17/11: TAG CMT. PLUG @ 3,313' (OK'D BY NMOCD); PUMP A 30 SX. CMT. SQZ. A 60 SX. CMT. PLUG @ 1,401'; WCC.  09/18/11: TAG CMT. PLUG @ 1,120'; PERF. X CIRC. TO SURF. A 140 SX.	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date  each wellbore diagram of proposed completion  ILE W/ FRESH WATER (PER NMCCD) BUT WAS  PLUG @ 2,750'-2,630' (CALC.); PERF. X  CMT. PLUG @ 311'-3'; DIG OUT X CUT OFF
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST ACCEMENT JOB L.  OTHER: OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion.  09/16/11: RIH W/ TBG. X TAG PBTD @ 3,662'; ATTEMPT TO WASH DOWN HOUNSUCCESSFUL; PUMP A 40 SX. OMT. PLUG @ 3,662'; WOC.  09/17/11: TAG OMT. PLUG @ 3,313' (OK'D BY NMOCD); PUMP A 30 SX. OMT. SQZ. A 60 SX. OMT. PLUG @ 1,401'; WOC.	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date  each wellbore diagram of proposed completion  ILE W/ FRESH WATER (PER NMCCD) BUT WAS  PLUG @ 2,750'-2,630' (CALC.); PERF. X  CMT. PLUG @ 311'-3'; DIG OUT X CUT OFF
PULL OR ALTER CASING	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.mm.us/ocd.  give pertinent dates, including estimated date  each wellbore diagram of proposed completion  ILE W/ FRESH WATER (PER NMCCD) BUT WAS  PLUG @ 2,750'-2,630' (CALC.); PERF. X  CMT. PLUG @ 311'-3'; DIG OUT X CUT OFF  TALL DRY HOLE MARKER.
PULL OR ALTER CASING	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date  each wellbore diagram of proposed completion  ILE W/ FRESH WATER (PER NMOCD) BUT WAS  PLUG @ 2,750'-2,630' (CALC.); PERF. X  CMT. PLUG @ 311'-3'; DIG OUT X CUT OFF  TALL DRY HOLE MARKER.
PULL OR ALTER CASING  MULTIPLE COMPLETION  CASING TEST ACCEMENT JOB IL  OTHER:  OTHER:  OTHER:  The complete operations of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion.  O9/16/11: RIH W/ TBG. X TAG PBTD @ 3,662'; ATTEMPT TO WASH DOWN HOUSUCCESSFUL; PUMP A 40 SX. CMT. PLUG @ 3,662'; WCC.  O9/17/11: TAG CMT. PLUG @ 3,313'(OK'D BY NMOCD); PUMP A 30 SX. CMT. SQZ. A 60 SX. CMT. PLUG @ 1,401'; WCC.  O9/18/11: TAG CMT. PLUG @ 1,120'; PERF. X CIRC. TO SURF. A 140 SX. WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X INS  WELL PLUCCED AND ABANDONED 09/18/11.  Thereby certify that the information above is true-and complete to the best of my know grade tank has been will be constructed or closed according to NMOCD guidelines X, a general per	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.mm.us/ocd.  give pertinent dates, including estimated date  each wellbore diagram of proposed completion  ILE W/ FRESH WATER (PER NMCCD) BUT WAS  PLUG @ 2,750'-2,630' (CALC.); PERF. X  CMT. PLUG @ 311'-3'; DIG OUT X CUT OFF  TALL DRY HOLE MARKER.
PULL OR ALTER CASING	PLUG AND ABANDONMENT  ABANDONME
PULL OR ALTER CASING  MULTIPLE  CASING TEST OF CEMENT JOB  CEMENT	PLUG AND ABANDONMENT  APProved for plugging of well bore only.  iability under bond is retained pending receipt  f C-103 (Subsequent Report of Well Plugging)  hich may be found at OCD Web Page under  orms, www.cmmrd.state.nm.us/ocd.  give pertinent dates, including estimated date  each wellbore diagram of proposed completion  ILE W/ FRESH WATER (PER NMOCD) BUT WAS  1. PLUG @ 2,750'-2,630' (CALC.); PERF. X  CMT. PLUG @ 311'-3'; DIG OUT X CUT OFF  TALL DRY HOLE MARKER.
PULL OR ALTER CASING	PLUG AND ABANDONMENT  ABOVED ABOUT ABANDONMENT  ABOVED ABO
PULL OR ALTER CASING	PLUG AND ABANDONMENT  ABANDONME