Submit 1 Copy To Appropriate District	State of New Mexico gy, Minerals and Natural Resources	Form C-103 October 13, 2009
District I Ener 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 50 BBS OCID II		WELL API NO. 30-005-00877 -
1301 W. Grand Ave., Artesia, NM 5521055 COMP11 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.
87505 SUNDRY NGTIGES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Rock Queen Unit
1. Type of Well: Oil Well Gas Well Other Injector		8. Well Number 40
Celero Energy II, LP		247128 🖌
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701		10. Pool name or Wildcat Caprock; Queen
4. Well Location		
Unit Letter <u>F</u> : <u>1980</u> Section 26	_feet from the <u>North</u> line and <u>198</u> Township 13S Range 31E	80 feet from the <u>West</u> line NMPM CountyChaves
	ation (Show whether DR, RKB, RT, GR, etc.,	
C-103 (Subsequent Report of Well bore only Which may be found at OCD Web Page Forms, www.emnrd.state.nm.us/ocd	receipt of ☐ COMMENCE DRI Dging) ☐ CASING/CEMEN under	
OTHER:	Directions (1) where all pertinent details and	d give pertinent dates including estimated date
13. Describe proposed or completed operations. (Crearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
 7/28/11 - Ran & set Kenco's cmt retainer @ to pump below retainer. Tried several times retainer. Unable to pump. TOH w/ tbg & cr 7/29/11 - TIH w/ tbg WS, 6- 3 1/8" DC"s @ retainer. Pushed cmt retainer to 2955'. Pum cmt retainer. Ran on tbg to 2900'. Pumped 2 BPM. Load & test tbg-csg annulus, held @ 7/30/11 - Pump 100 sx Class "C" cmt w/ 29 retainer, pump 25 sx of Class "C" cmt w/ 29 Tag @ 2540'. Circ 10 bbls of 9.6 ppg of mt 2140'. TIH w/ tbg & 4 ½" AD-1 pkr. Ran to 	s w/ psi ranging from 1000#-2000#. Unstung nt retainer stinger. & 3 7/8" OD bit. Ran & tag @ 2900'. D/O cr ped into csg leak @ 2948' w/ 2 BPM & 350# 5 BPW through same. Set retainer @ 2900'. I ok. % CaCl2 & displace to top of retainer @ 290 % CaCl2. Spot the 25 sx on top of retainer @ id laden fluid from 2540' back to 1890'. Perf o 1891'. Pump 40 sx of Class "C" cmt w/ 2%	g WS & stung into retainer @ 2900'. Unable from retainer & circ well. Sting back into mt retainer in 2 ½ hrs. Lost circ while drlg # psi w/ 10 BPW. TIH w/ tbg & 4 ½" Kenco Pumped 15 BPW through retainer @ 350# &
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE LUSA HUN	TITLE Regulatory Analyst	DATE_08/16/2011
Type or print name <u>Lisa Hunt</u>	E-mail address: <u>lhunt@celeroene</u>	ergy.com PHONE: (432)686-1883
For State Use Only	1 / care	- 0
APPROVED BY: Conditions of Approval (if any):	La-HTTLE JTHIT WE	DATE 9-27-2011
\mathcal{O}		SED 2 7 2011

 \mathbf{x}

SEP 2 7 2011

Rock Queen Unit # 40 - C103 continued

8/1/11 - Lwr tbg & tag @ 2017'. Circ 9.6# mud laden fluid from 2017'-1367'. TOH w/ tbg & pkr. Perf 4 ½" csg w/ 3 1/8" cased gun w/ 4 holes @ 1520'. Set pkr @ 1191'. Pump 40 sx Class "C" cmt. Displaced to 1353' (2.5 below pkr) @ 400# SD psi. Lower tbg & tag @ 1515'. Had only 5' of fill. TOH w/ tbg & pkr. Perf 4 ½" csg @ 250'.

8/2/11 - Lwr tbg & tag @ 1350'. C/O & wash out green cmt from 1350'-1476' (cmt started firming up @ 1450'). TOH w/ tbg & bit. Ran tbg open ended to 1476'. Spot 10 sx of cmt @ 1476', bringing TOC to 1324'. Pump 20 bbls of 9.6# mud laden fluid from 1324'-44' FS. TOH w/ tbg, leaving 1 jt @ 30'. Pump 80 sx of Class "C" cmt w/ 2% CaCl2 & circ cmt to surface out the 4 ½" csg, 4 ½" x 5 ½" csg annulus & 5 ½" x 8 5/8" csg annulus. Finished pulling the 1 jt of tbg out of hole. NDBOP. Fill csgs to surface w/ cmt.

<u>8/3/11</u> - Cut off 8 5/8" WH & csg, 5 ½" & 4 ½" csgs, 3' below ground level. Weld on cap. Install dry hole marker. Clean location & RDMO. Well now P&A.