

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I  
1625 N French Dr, Hobbs, NM 88240

HOBBS OCD

1220 South St. Francis Dr.  
Santa Fe, NM 87505

DISTRICT II  
1301 W Grand Ave, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

SEP 29 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		WELL API NO 30-025-07516
1 Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5 Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2 Name of Operator Occidental Permian Ltd.		6 State Oil & Gas Lease No
3 Address of Operator HCR 1 Box 90 Denver City, TX 79323		7 Lease Name or Unit Agreement Name North Hobbs(G/SA) Unit Section 32
4 Well Location Unit Letter A 330 Feet From The North 330 Feet From The East Line Section 32 Township 18-S Range 38-E NMPM Lea County		8 Well No 411
11 Elevation (Show whether DF, RKB, RT GR, etc ) 3658' DF		9 OGRID No. 157984
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10 Pool name or Wildcat Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ Multiple Completion ☐  
OTHER Clean out/Perf/Acid treat ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Kill well.
2. POOH w/ESP equipment.
3. Clean out to PBTD @4445'.
4. Perforate well @4300-04, 4314-24', 4352-64', 4376-84', 4402-18'.
5. Acid treat well w/1500 w/15% PAD acid.
6. Perform scale squeeze.
7. Run back in hole w/ESP equipment.
9. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 09/28/2011  
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy\_johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only

APPROVED BY [Signature] TITLE Staff Manager DATE 10-3-2011  
CONDITIONS OF APPROVAL IF ANY

OCT 03 2011