

HOBBS OGD

OCT 11 2011

RECEIVED

## CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-11722

5. Indicate Type of Lease

STATE ☐FEE ☒

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name:

Ida Wimberley

8. Well No. 13

9. OGRID Number

240974

10. Pool name or Wildcat SWD; San Langille Mattix-7KVRS-QN-GB Andres

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator

Legacy Reserves Operating LP

3. Address of Operator

PO Box 10848, Midland, TX 79702

4. Well Location

Unit Letter M : 330 feet from the West line and 330 feet from the South line

Section 24 Township 25-S Range 37-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3079' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE ☐  
COMPLETION ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

09/19/11 MIRU plugging equipment.

09/20/11 Wait on orders and tbq.

09/21/11 NU wellhead. RIH w/ tbq in #2 and tagged plug @ 3270'. Picked up swival and tried to circulate hole. Pumped 180 bbls. Called Berry Johnson and was told to GIH in #3. Lay down swival, POH w/ 1 1/4 tbq. Change over wellhead.

09/22/11 RIH w/ bit and tagged up @ 3 ft. NU stripper head and tried to drill. Made 2 ft. Stand by for orders. Rigged down reverse rig. Changed over to #2. RIH w/ 1 1/4 tbq in #2 to 3270' and came out laying down. Tied onto #2 27/8 csg. Sqz'd 150 sx cement and pressured up to 300 psi. Close well in.

09/23/11 Checked well and cement at surface. Rigged down and moved off.

10/05/11 Moved in backhoe and welder. Dug out cellar, cut off wellhead, Welded on Dry Hole Marker. Backfilled cellar. Buried deadmen. Cleaned location and moved off.

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms, www.cmnrd.state.nm.us/oed.I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to MOCOD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.SIGNATURE Berry Johnson TITLE Production Superintendent DATE 10/07/11Type or print name Berry Johnson

E-mail address:

Telephone No. 432.689.5200

For State Use Only

APPROVED BY [Signature] TITLE Staff Mgr DATE 10-12-2011

Conditions of Approval (if any):

OCT 13 2011