

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

HOBBS OCD  
OCT 11 2011  
RECEIVED

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-38036
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name BADGER STATE
8. Well Number 1
9. OGRID Number 131559
10. Pool name or Wildcat <del>Mississippian</del> MORTON (WOLFCAMP)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator PURVIS OPERATING CO.	
3. Address of Operator PO BOX 51990, MIDLAND, TX 79710-1990	
4. Well Location Unit Letter <u>P</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>6</u> Township <u>15S</u> Range <u>35E</u> NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4060' KB	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Temporarily Abandon ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9-24-2011 Reach TD 11,000'. Run open hole logs.  
9-25-2011 Set 25 sks Class H cement plugs per OCD instructions as follows:  
1<sup>st</sup> plug - 10,985' - Bottomhole plug  
2<sup>nd</sup> plug - 9,669' - Wolfcamp plug  
3<sup>rd</sup> plug - 8,159' - Abo plu  
4<sup>th</sup> plug - 7,405' - Tubb plug  
5<sup>th</sup> plug - 6,118' - Glorieta plug  
6<sup>th</sup> plug - 4,671' - Intermediate csg shoe. Well TA.

Spud Date:

August 4, 2011

Rig Release Date:

September 25, 2011

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Donnie E. Brown*

TITLE

Petroleum Engineer

DATE October 7, 2011

Type or print name

Donnie E. Brown

E-mail address:

eng@purvisop.com

PHONE: 432-682-7346

For State Use Only

APPROVED BY:

*[Signature]*

TITLE

*Staff Mgr*

DATE 10-12-2011

Conditions of Approval (if any)

OCT 13 2011