Submit I Copy To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-00285
1301 W. Grand Ave., Artesia, NM 88210 CONSERVATION DIVISION District III 1220 South St. Francis Dr.			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 Control Francis Dr.			STATE X FEE
District IV OCT 1 C 00 Banta Fe, NW 8/303			6. State Oil & Gas Lease No.
87505			303735
SUNDRY NOTICES AND TREPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name ROCK QUEEN UNIT
1. Type of Well: Oil Well Gas Well Other Injector			8. Well Number 108
2. Name of Operator			9. OGRID Number
Celero Energy II, LP			247128
3. Address of Operator 400 W. Illinois, Ste. 1601			10. Pool name or Wildcat
Midland, TX 79701 4. Well Location			Caprock; Queen
<u> </u>			
Unit Letter P ; 660' feet from the S line and 990' feet from the E line			
Section 19 Township 13S Range 32E NMPM CountyLEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4380' KB			
(1900 to the control of the control	1000 110		
12. Check A	Appropriate Box to Indicate N	ature of Notice. I	Report or Other Data
,			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON			
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMENT	JOB []
DOWN TOLL COMMINGE			
OTHER:		OTHER:	·
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. RIH w/ BP, PS, & 2,3/8" workstring to 3060'. Spot 25 sx Class C, POOH to 2000', wait 4 hrs & tag TOC at/above 2960'. Circ			
salt mud to 2253'. V = 0 K			
2. Perf 4 @ 2253'. Run pkr & with the 4" by 5 1/2" annulus loaded & closed, sqz 40 sx Class C. WOC 2 hrs, POOH w/ pkr & tbg &			
RBIH w/ BP & PS on tbg to tag TOC at/above 2153'. POOH w/tbg. 3. Free point 4", back off & recover.			
4. RIH w/ BP & PS on the to 50' below 4" stub & spot 25 sx Class C. POOH 1000' or so and WOC 4 hrs. RBIH & tag TOC at			
/above 50' above 4" stub. Circ salt mud to 1558'.			
5. RD workover unit.			
 RU contract P&A equipment. Perf 4 @ 1558'. RIH w/pkr & sqz 40 sx. POOH w/pkr, RBIH & tag TOC at/above 1458' after 4 hrs WOC. Circ hole full of salt 			
mud.			
8. Perf 4 @ 271'. RIH w/ tbg to 321' & fill 5 1/2" and 5 1/2" by 8 5/8" to surf w/ 90 sx Class C. POOH.			
9. Cut off WH's, set P&A marke	r, clean & reclaim location.		
*Setting 1st plug tomorrow 10/19	9/11		
Spud Date.	Rig Release Da	ite:	
			,
Thomas and futbat the information			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
\mathscr{L} . \mathscr{L}			
SIGNATURE SIGNATURE	TITLE Regula	tory Analyst	DATE 10/18/2011
Type or print name Lisa Hunt	E-mail address	: <u>lhunt@celeroener</u>	gy.com PHONE: (432)686-1883
For State Use Only	/ / /	_	
APPROVED BY:	TITLE S	TAH MG	DATE 10-19-20
Conditions of Approval (if any):	<u></u>		DAIL!



