HOBBS OCD

| Submit One Copy To Appropriate Distract 18 2011 Office State of New Mexico | Form C-103 |
|--|---|
| Digital Line Digit | Revised August 1, 2011 |
| 1625 N. French Dr., Hobbs, NM 88240 | WELL API NO. 30-025-11722 |
| 811 S. First St., Grand Ave., Artesia, NM OIL CONSERVATION DIVISION | 5. Indicate Type of Lease |
| 88210 District III 1220 South St. Francis Dr. | STATE FEE |
| 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| District IV 1220 S. St. Francis Dr., Santa Fé, NM | |
| 87505 SUNDRY NOTICES AND REPORTS ON WELLS | 7 Longo Nomo on Huit A may from Nome |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name Ida Wimberley |
| 1. Type of Well: Oil Well Gas Well Other SWD | 8. Well Number 13 |
| 2. Name of Operator | 9. OGRID Number |
| Legacy Reserves Operating LP 3. Address of Operator | 240974 |
| P.O. Box 10848 Midland, TX 79702 | 10. Pool name or Wildcat SWD; San Andres |
| 4. Well Location | / / |
| Unit Letter M: 330 feet from the West line and 330 feet from the South | line / |
| Section <u>24</u> Township <u>25S</u> Range <u>37E</u> NMPM County <u>Lea</u> | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3079' GR | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da | nta |
| | |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL | |
| <u> </u> | |
| TEMPORARILY ABANDON | _ |
| CASING/CEMENT | 30B |
| OTHER: | ady for OCD inspection after P&A |
| All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. | |
| Rat hole and cellar have been filled and leveled. Cathodic protection holes have been p A steel marker at least 4" in diameter and at least 4' above ground level has been set in | roperly abandoned. |
| A steel marker at least 4" in diameter and at least 4' above ground level has been set in | concrete. It shows the |
| OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR | |
| UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR | |
| PERMANENTLY STAMPED ON THE MARKER'S SURFACE. | |
| ☐ The location has been leveled as nearly as possible to original ground contour and has b | een cleared of all junk trook flow lines and |
| other production equipment. | |
| Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. | |
| If this is a one-well lease or last remaining well on lease, the battery and pit location(s) | have been remediated in compliance with |
| OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produ | - |
| from lease and wall leastion | ction equipment and junk have been removed |
| from lease and well location. | ction equipment and junk have been removed |
| from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) | ction equipment and junk have been removed |
| from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. | ed. (Poured onsite concrete bases do not have |
| from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. | ed. (Poured onsite concrete bases do not have |
| from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. | ed. (Poured onsite concrete bases do not have |
| from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- |
| from lease and well location. All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- |
| All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sche | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- dule an inspection. |
| All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sche SIGNATURE Buy Dome TITLE Production Superior | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- dule an inspection. |
| All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sche SIGNATURE TITLE Production Supering Type OR PRINT NAME Berry Johnson E-MAIL: | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- dule an inspection. |
| All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sche SIGNATURE Buy Dome TITLE Production Superior | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- dule an inspection. |
| All metal bolts and other materials have been removed. Portable bases have been remove to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to sche SIGNATURE TITLE Production Supering Type OR PRINT NAME Berry Johnson E-MAIL: | ed. (Poured onsite concrete bases do not have All fluids have been removed from non- dule an inspection. |

OCT 2 0 2011