FORM APPROVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

	OM B No. 1004-013
- OCD	Expires: March 31, 2

(April 2004).	UNITEDSTATE	23		OM B No.	1004-013/
. D	EPARTMENT OF THE	INTERIOR	-ac OCD	Expires: M	farch 31, 2007
BU	REAU OF LAND MAN	AGEMENT	HOBBS OCD	5. Lease Serial No.	
			2 30,	\\L	C 031740 B
SUNDRY	NOTICES AND REPO	ORTS ON WELLS	" OCT 20 50'	6. If Indian, Allottee or Tr	ribe Name
Do not use this	form for proposals t	o drill or to re-enter a	, 00.		
	•	PD) for such proposa	is sectivi	If Unit of CA / Agreem	ent, Name and/or No.
	LICATE - Other ins	ructions on reverse s	side. REGE		
1. Type of Well				8. Well Name and No.	
Oil Well	Gas Well	Other		Mey	rer B 4 #028 /
2. Name of Operator	ConocoPi	nillips Company		9. API Well No. 30-	.025-23931
3a. Address		3b. Phone No. (include a	rea code)	10. Field and Pool, or Expl	loratory Area
P.O. Box 51810 Midlar	nd, TX 79710	432-688-68	84	Oil Ce	nter Blinebry
4. Location of (Footage, Sec., T., R, o	r Survey Descriptign)			11. County or Parish, State	e
UL X, 2230' FSL 8	1980' FEL Se	ec 4, T-21-S, R-36-E		Lea	County, NM
12. CHECK APPRO	OPRIATE BOX(ES) T	O INDICATE NATUI	Œ OF NOTICE, R	EPORT, OR OTHER DA	TA
TYPE OF SUBMISSION			TYPE OF A	CTION	
[] N. C. C. C.	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-off
✓ Notice of Intent	Alter Casing	Fracture	Treat F	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Con	structión E	Recomplete	Other
<u> </u>	Change Plans	✓ Plug and	Abandon	Cemporarily Abandon	
Final Abandonment Notice	Convert to Inject	etion Plug Bac	k U	/ater Disposal	
13. Describe Proposed or Completed C the proposal is to deepen directionally of the Bond under which the work will be completion of the involved operations. completed. Final Abandonment Notice ready for final inspection.)	or recomplete horizontall performed or provide the If the operation results i	y, give subsurface locations bond No. on file with the multiple completion or a	ns and measured and e BLM / BIA. Requirecompletion in a nev	true vertical depths of all per ired subsequent reports shall be w interval, a Form 3160-4 sha been completed, and the oper	rtinent markers and zones. Attach be filed within 30 days following all be filed once testing has been

1) MIRU. ND WH, NU BOP.

2) Set CIBP @ 5765'. RIH Tbg - Tag BP. Circ hole w/ MLF. Cap w/ 30sx cmt @ 5765'-5555' - Tag

3) Spot 20sx cmt @ 5203'-5103' 25 Sx Min 5278 - 5/28

4) Spot 25sx cmt @ 4047'-3853' - Tag

5) Spot 40sx cmt @ 3620'-3285'

5) Spot 40sx cmt @ 3620'-3285'
6) Spot 20sx cmt @ 2900'-2800' Z5 SX Min 2915 - Z785 SEE ATTACHED FOR CONDITIONS OF APPROVAL

ATTACHED

7) Perf & Sqz 60sx cmt @ 2635'-2453' - Tag 8) Perf & Sqz 60sx cmt @ 1350'-1170' - Tag

9) Perf & Sqz 30sx cmt @ 60'-3'

10) Fill wellbore. RDMO. Cut off wellhead & anchors. Clean location, Install P&A marker.


* Ground level DHM (see Atta	ohed					
14. I hereby certify that the following is true and correct						
Name						
Greg Bryant	Title	F	P&A Tech			
Signature	Date		9/14/11			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by James Q. Como	Title	SEAS	Date	10-16-11		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights						
in the subject lease which would entitle the applicant to conduct operatins thereon.	Office	CF0				

Title 18 U.S.C., Section 1001 and Title 43 U.S.C., Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WELLBORE SKETCH ConocoPhillips Company -- Lower 48 - Mid-Continent BU / Permian Operations

RKB @	3587'						Date A	pril 14, 2	2011	
DF @	3586'		2.1							
GL @	3576'		Subarea		Hobbs					_
			Lease & We Legal Descr		Meyer B-4			265 111	W 191	
111	1 12	12-1/4" Hole	Legal Desci	iption		. & 1980' FEL, S	Sec 4, 1215, R	36E, UL	. "J"	
, 4	13		County		Lea	State	New Mexic			_
1.11			Field	Oil Cente	er Blinebry			-		
	اذ		Spud	2/12/72		Rig Relea	ised 3/5/7	'2		_
	~		API Number	· , ———	30-025-2393	1				_
,			Status	·			INI	10001	7.455	_
をいまる。						LSe Se	erial No.	LC031	740B	
	ţ'		Stimulation	History:						
[2]	妈						Lbs. M	lax	Max	(
15			<u>Interval</u>	<u>Date</u>	Type	<u>Gals</u>	Sand P	ress I	ISIP Rat	
왕	80 S	Top Salt @ 1220'								
18] [1 21	8-5/8" 20# @ 1227'								
		Cmt'd w/ 600 sx, circ TOC @ Surface		3/11/72	Perforate w/1 S					
		TOC @ Surface	6154-6176	3/12/72	5922, 5911, 590 28% NEFE HCI	6, 5904, 5902, 8 1,200	5889, 5877 and	5865 (1	4 holes)	
			6154-6176	3/12/72	Gelled Water	3,000	4	700 2	2250	
			5865-5922	3/13/72	28% NEFE HCI	1,200				
			5865-5922	3/13/72	Gelled Water	3,000	4	100 1	1600	
			5865-6176	8/7/75	15% NE	300				
			#### A:==	4/23/76	Hot Oil casing					
			5865-6176	2/19/79	15% NE	500				
				1/24/85 9/25/85	Tag fill @ 6231' Tag fill @ 6231'					
11				8/10/90	Tag bridge @ 61			5-6295		
	1		5865-6176	8/13/90	15% NEFE HCI	900	, scale @ 020.	7-0233		
11		Base Salt @ 2508'		9/24/10	Heavy paraffin d					
	Lan.			9/29/10	Perforate circula					
22 c. 24 c. 24 c. 24 c. 24	*	TOC 5-1/2" Csg @ 2690' (CBL)		10/5/10	POOH laying do	wn rods and tub	oing			
13	\$				•					
i.	÷									
7	X.									
[3]	4									
72										
ئم	<u>@</u>									
#g 1.00	5/									
1,5	7	•								
[.]	₹ <u>₹</u>									
	8									
121	72									
	100	DV Tool @ 3997'								
A the state of the	がある。 1970年の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の	9								
8 of 2 of 2	£	•								
	20								•	
27	1									
	et l		•							
35	*									
	5									
<u> </u>	#15- HER- 184									
[2]	劉									
7	\$g									
4										
3	Ž.									
<u> </u>	髭									
9-X 1-15:										
22	==	5865 5877 5889								
==	==	5902 5904 5906			Formation To	ops:				
==	EE	5911 5922			Rustler	1220'	Penrose	3	467'	
		2454 2452 2422			Salado	1350'	Grayburg		620'	
==	==	6154 6156 6168 6170 6173 6176	•		Tansıll	2503'	San And	res 39	903'	
₂ 2	<u></u>	6170 6173 6176			Yates	2635'	Glorieta		203'	
		7-7/8" Hole			Seven Rivers		Blinebry	Mkr 56	605'	
أهدا يتاميك		5-1/2" 14# & 15.5# @ 6335'			Queen	3335'				
PBTD @	6231'	Cmt 1st Stage 350 sx								
TD @	6335'	Cmt 2nd Stage 225 sx								
_		TOC @ 2690' (CBL)								

WELLBORE SKETCH ConocoPhillips Company -- Lower 48 - Mid-Continent BU / Permian Operations



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ¼ ¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼ ¼ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
 - 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Environmental Protection Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979